



Project: Greenacres Elementary School	Date: 01-17-20
Address: 41 Huntington Ave, Scarsdale, NY 10583	Job ID / MU #:
Client: Scarsdale CSD	Weather: Clear~25deg F

Inspection Type: Noise and Dust Monitoring	Contractor: Park East Construction
Present At Site: Don Herlihy	Sub-Contractor:
General Area: North Side of School	CM/Designer:
Specific Location: North side of School in the basement, 1st and 2nd Floor	
Last Inspection:	Building Code Section:
Reviewed Approved	Drawings:
	Submittals
	Other:

Deficiency:	Resolution:

Request For Information:					
Non-Conformance Report:					
RFI # : <input type="checkbox"/> Issued	RFI # : <input type="checkbox"/> Answered	NCR # : <input type="checkbox"/> Issued	NCR # : <input type="checkbox"/> Resolved	NCR # : <input type="checkbox"/> Open	

Observations/Notes:

On site for the on going monitoring of construction Noise and Dust for Greenacres Elementary School.

Noise Monitoring- Readings were taken in the Art room and Library (Basement and 1st Floor) which is closest to the construction zone. Average readings were 53.87 dBA. Readings from 730a to 930a were also taken in the 1st floor hallway by closed off corridor, meter moved after showing no indication of high noise levels. Moved to basement next to art room at 930a.

Dust Monitoring- Readings taken are as show on page 2 of this report. Particle Counter had technical issues and was not able to collect readings after 12pm.

Work performed today- Concrete placement. Concrete pump was staged from 7a to 1030a by Library and Art Room Window area. Pump was then moved over to Sage Terrace for remainder of concrete placement. Ironworkers were also on site for the bolting and erection of steel. Other miscellaneous work was done in the enclosed heated area of the addition.

Attachments/Photos :

Time on site: 7a	Time off site: 330p
------------------	---------------------

Inspected Work Satisfactory (Except As Noted): <input checked="" type="checkbox"/> No: <input type="checkbox"/>	Re-inspection Required: <input type="checkbox"/>	Work Completed: <input checked="" type="checkbox"/>
---	--	---

Inspector: Sean Donnelly Signature:  Certification: _____



375 RABRO DRIVE, HAUPPAUGE NY 11788
• TEL: (631) 761-5555 • www.mtllab.net
NYC DoB Special Inspection Agency #0230

REPORT #
SD11720

PHOTOS TAKEN

INSPECTION REPORT

Page 2 of 6

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
01-17	730a	North side 2nd and 1st floor hallways	1	1	2	72.3	24.8
	845a	Basement	2	1	2	68.9	22.1
	900a	1st floor-Library	3	1	2	70.9	22.2
	910a	2nd floor	4	2	5	75.6	30.5
	1000a	Basement	5	0	0	64.2	25.6
	1005a	1st Floor- North side including library	6	1	3	71.2	32.4
	1015a	2nd Floor	7	0	2	75.9	22.3
	1115a	Basement	8	3	5	73.0	25.8
	1125a	1st Floor North side including library	9	1	3	72.1	23.5
	1135a	2nd Floor	10	0	2	75.4	24.7
	1200p	Basement	11	2	5	67.8	26.7

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.




INSPECTION REPORT

Photo 1



Photo 2



Inspector: Sean Donnelly Signature:  Certification: _____

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and its conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



Photo 3




Photos 4,5



Inspector: Sean Donnelly Signature:  Certification: _____

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17


Standard Sound Level Meter RealTime Graph
Time: 2020-1-17 15:9:5



Start Time: 17-01-2020,8:52:39
Maxnum: 85.90 17-01-2020,11:23:38
Minnum: 41.10 17-01-2020,15:16:05
Sample Rate: 1.00
Average: 53.82

Meter 1 in library

Standard Sound Level Meter RealTime Graph
Time: 2020-1-17 15:12:7



Start Time: 17-01-2020,14:47:03
Maxnum: 85.10 17-01-2020,14:50:51
Minnum: 46.80 17-01-2020,14:51:35
Sample Rate: 1.00
Average: 49.89

Meter 2 - reading taken in basement