



Project: Greenacres Elementary School	Date: 01-22-20
Address: 41 Huntington Ave, Scarsdale, NY 10583	Job ID / MU #:
Client: Scarsdale CSD	Weather: Clear~25deg F

Inspection Type: Noise and Dust Monitoring	Contractor: Park East Construction
Present At Site: Don Herlihy	Sub-Contractor:
General Area: North Side of School	CM/Designer:
Specific Location: North side of School in the basement, 1st and 2nd Floor	
Last Inspection:	Building Code Section:
Reviewed Approved	Drawings:
	Submittals
	Other:

Deficiency:	Resolution:			
Request For Information:				
Non-Conformance Report:				
RFI # : <input type="checkbox"/> Issued	RFI # : <input type="checkbox"/> Answered	NCR # : <input type="checkbox"/> Issued	NCR # : <input type="checkbox"/> Resolved	NCR # : <input type="checkbox"/> Open
Observations/Notes:				
<p>On site for the on going monitoring of construction Noise and Dust for Greenacres Elementary School.</p> <p>Noise Monitoring- Readings were taken in the Library (meter 1) and 1st floor hallway near vacant corridor(meter 2). Average reading was 51.82 dBA in the library. Average reading was 54.68dBA in the 1st floor hallway. High levels observed in meter 2 were local noise from students passing through the hallway. No observations of construction noise was noticed during rounds.</p> <p>Dust Monitoring- Readings taken are as show on page 2 of this report. High levels were observed from 1010am reading. Levels were all high in the 1st floor gym corridor and 2nd floor. Park East and Contractor were both notified immediately.</p> <p>Work performed today- Masonry CMU, Steel erection, Rebar/Formwork Installation for foundation, chopping and excavation by vacant corridor to school.</p>				
Attachments /Photos :				
Time on site: 7a		Time off site: 330p		

Inspected Work Satisfactory (Except As Noted): ☒ No: ☐ Re-inspection Required: ☐ Work Completed: ☒

Inspector: Sean Donnelly Signature:  Certification: _____

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



375 RABRO DRIVE, HAUPPAUGE NY 11788
• TEL: (631) 761-5555 • www.mtllab.net
NYC DoB Special Inspection Agency #0230

REPORT #
SD12220

PHOTOS TAKEN

INSPECTION REPORT

Page 2 of 5

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
01-21	730a	1st Floor and Library	1	2	5	57.6	53.2
	735a	2nd Floor	2	2	4	59.2	53.6
	740a	Basement	3	2	5	66	50.6
	840a	Basement	4	8	16	61.5	40.7
	845a	1st floor Gym Corridor West	5	17	33	63.3	48.8
	850a	1st Floor Gym Corridor East	6	19	33	62.1	48.6
	855a	2nd floor corridor	7	3	8	65.7	40.7
	1000a	Basement	8	8	13	64.6	40.7
	1010a	1st Floor Gym Corridor West (Park East Notified)	9	53	94	64.6	45.6
	1015a	1st floor Gym Corridor East	10	50	88	65.7	47.5
	1020a	2nd Floor	11	67	96	74.3	41.9
	1045a	1st Floor Gym Corridor East(problem identified)	12	29	58	68.5	46.9
	1050a	1st Floor Gym Corridor West	13	30	59	68.4	46.8
	1055a	2nd Floor	14	62	92	69.4	46.4
	1105a	1st floor Gym Corridor East	15	22	42	75.4	44.2
	1115a	2nd Floor	16	31	61	69.8	45.5
	1200p	Basement	17	7	12	73.0	38.9
	1205p	1st floor	18	18	33	71.4	40.4

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.



375 RABRO DRIVE, HAUPPAUGE NY 11788
• TEL: (631) 761-5555 • www.mtllab.net
NYC DoB Special Inspection Agency #0230

INSPECTION REPORT

REPORT #

PHOTOS TAKEN


Page 3 of 5

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
	1210p	2nd floor	19	8	17	73.4	43.2
	1p	Basement	20	4	10	77.5	34.1
	110p	1st Floor Gym Corridor	21	7	14	75.9	38.8
	115p	2nd Floor	22	8	15	75.6	40.0
	210p	Basement	23	2	6	78.2	31.7
	215p	1st Floor Gym Corridor	24	8	14	78.6	35.4
	220p	1st Floor Gym Corridor	25	3	9	77.4	37.5

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.


Standard Sound Level Meter RealTime Graph
Time: 2020-1-22 14:54:48



Start Time: 22-01-2020,8:52:11
Maxnum: 84.30 22-01-2020,11:42:12
Minnum: 37.60 22-01-2020,14:34:27
Sample Rate: 1.00
Average: 51.82

Meter 1 in Library

Standard Sound Level Meter RealTime Graph
Time: 2020-1-22 14:58:0



Start Time: 22-01-2020,7:37:23
Maxnum: 94.30 22-01-2020,12:10:17
Minnum: 40.40 22-01-2020,12:41:50
Sample Rate: 1.00
Average: 54.68

Meter 2 in 1st Floor Hallway