



MUNICIPAL
TESTING LABORATORY, INC.

INSPECTION REPORT

REPORT #

SAMPLES TAKEN

Page of

| | |
|---|-----------------|
| Project: Greenacres School | Date: 09/06/19 |
| Address: 41 Huntington Avenue, Scarsdale NY 10583 | Job ID / MU #: |
| Client: Park East Construction | Weather: Cloudy |

| | |
|---|------------------------|
| Inspection Type: Noise and Dust Monitoring | Contractor: Park East |
| Present At Site: 7:00AM | Sub-Contractor: |
| General Area: Northern Yard of School | CM/Designer: |
| Specific Location: Northern Side of school 1st, 2nd floor, Basement | |
| Last Inspection: | Building Code Section: |
| Reviewed | Drawings: |
| Approved | Submittals |
| | Other: |

| | | | | |
|---|---|---|---|---------------------------------------|
| Deficiency: | Resolution: | | | |
| Request For Information: | | | | |
| Non-Conformance Report: | | | | |
| RFI # : <input type="checkbox"/> Issued | RFI # : <input type="checkbox"/> Answered | NCR # : <input type="checkbox"/> Issued | NCR # : <input type="checkbox"/> Resolved | NCR # : <input type="checkbox"/> Open |
| Observations/Notes: | | | | |

Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the library, Gymnasium, Cafeteria, and an overall walkthrough of the school.

An average noise reading of 45.8 dB/hr was measured for the day.

Dust Levels within the Perimeter of the school were measured. These Readings can be found in the chart on the next page.

Work today included: Excavation and placement of 3" River rock.

Attachments/Photos:

Time on site: 7:00 AM

Time off site: 3:30 PM

Inspected Work Satisfactory (Except As Noted): ☒ No: ☐ Re-inspection Required: ☐ Work Completed: ☐

Inspector: Erald Hysaj Signature:  Certification: _____

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



375 RABRO DRIVE, HAUPPAUGE NY 11788
 • TEL: (631) 761-5555 • www.mtllab.net
 NYC DoB Special Inspection Agency #0230

INSPECTION REPORT

REPORT #

PHOTOS TAKEN

Page of

Sept

| Date | Time | Location | Sample | 2.5 microns | 10 microns | Temp | RH% |
|-------|-------|-----------|--------|-------------|------------|------|------|
| 06/19 | 07:19 | Gymnasium | 1 | 0 | 1 | 71.8 | 68.5 |
| | 07:28 | 1st floor | 2 | 0 | 2 | 70.9 | 76.1 |
| | 07:37 | Library | 3 | 1 | 2 | 69.1 | 70.1 |
| | 08:31 | 1st floor | 4 | 1 | 2 | 68.5 | 83.0 |
| | 08:48 | 2nd floor | 5 | 2 | 4 | 69.3 | 71.3 |
| | 09:05 | 1st floor | 6 | 2 | 4 | 71.8 | 68.5 |
| | 09:12 | Cafeteria | 7 | 1 | 3 | 72.3 | 67.1 |
| | 09:20 | Gymnasium | 8 | 0 | 2 | 72.5 | 78.1 |
| | 10:41 | Basement | 9 | 1 | 2 | 73.9 | 60.3 |
| | 10:50 | 2nd floor | 10 | 2 | 4 | 75.8 | 73.2 |
| | 10:58 | 1st floor | 11 | 0 | 1 | 75.1 | 67.4 |
| | 11:05 | 1st floor | 12 | 1 | 3 | 75.4 | 67.9 |
| | 11:12 | 2nd floor | 13 | 0 | 1 | 78.9 | 69.3 |
| | 11:18 | Cafeteria | 14 | 1 | 2 | 68.9 | 68.0 |
| | 12:39 | 1st floor | 15 | 1 | 1 | 72.9 | 68.9 |
| | 12:42 | Library | 16 | 1 | 2 | 67.0 | 67.3 |
| | 12:54 | Basement | 17 | 0 | 0 | 71.2 | 68.9 |
| | 13:03 | 1st floor | 18 | 1 | 1 | 73.1 | 68.9 |

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction success. The field representative is not responsible for identifying errors and omissions in the contract documents.

375 RABRO DRIVE, HAUPPAUGE NY 11788
• TEL: (631) 761-5555 • www.mtllab.net
NYC DoB Special Inspection Agency #0230

INSPECTION REPORT

REPORT #

PHOTOS TAKEN


Page of

[illegible]

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.


Standard Sound Level Meter RealTime Graph
Time: 2019-9-6 10:40:50



Start Time: 06-09-2019,7:22:32
Maxnum: 67.10 06-09-2019,7:56:39
Minnum: 37.10 06-09-2019,7:23:49
Sample Rate: 1.00
Average: 44.62

GYMNASIUM NOISE LEVELS


Standard Sound Level Meter RealTime Graph
Time: 2019-9-6 10:44:49



Start Time: 06-09-2019,8:06:18
Maxnum: 84.20 06-09-2019,9:35:12
Minnum: 38.90 06-09-2019,8:09:02
Sample Rate: 1.00
Average: 52.80

KINDERGARTEN ART CLASS WITH STUDENTS


Standard Sound Level Meter RealTime Graph
Time: 2019-9-6 15:3:10



Start Time: 06-09-2019,11:02:19
Maxnum: 71.40 06-09-2019,11:03:11
Minnum: 33.60 06-09-2019,11:52:04
Sample Rate: 1.00
Average: 36.57

LIBRARY NOISE LEVELS

Standard Sound Level Meter RealTime Graph
Time: 2019-9-6 15:3:56



Start Time: 06-09-2019,12:17:49
Maxnum: 73.40 06-09-2019,13:43:03
Minnum: 35.30 06-09-2019,12:56:27
Sample Rate: 1.00
Average: 41.44

LIBRARY NOISE LEVELS