

375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

| bob opecial inspection rigericy wo200 | |
|---------------------------------------|----------------|
| INSPECTION REPORT | |
| | EWOMEN CHARGES |

| SAMPLES | TAKEN |
|---------|--------------|

REPORT #

Page of

| Date: 09/09/19 | | | | | |
|--|--|--|--|--|--|
| | | | | | |
| 7 | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| ess: 41 Huntington Avenue, Scarsdale NY 10583 Job ID / MU #: t: Park East Construction Weather: Sunny Sub-Contractor: Park East | | | | | |
| Idented Ale Huntington Avenue, Scarsdale NY 10583 Job ID / MU #: Weather: Sunny | | | | | |
| | | | | | |
| | | | | | |
| Other: | | | | | |
| Deficiency: Resolution: | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| RFI# : Issued RFI# : Answered NCR# : Issued NCR# : Resolved NCR# : Open | | | | | |
| Observations/Notes: | | | | | |
| Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the library, next to the work performed today. An average noise level of 44.10 dB was measured for the day. | | | | | |
| Dust Levels within the Perimeter of the school were measured. These Readings can be found in the chart on the next page. Work today included: Excavation of soil, Rebar installation, and Excavation. | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Seesage 14 Huntington Avenue, Scarsdale NY 10583 Iob ID / MU #: Park East Construction Weather: Sunny | | | | | |
| | | | | | |
| | | | | | |

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT #

PHOTOS TAKEN

INSPECTION REPORT

Page of

| Date | Time | Location | Sample | 2.5 microns | 10 microns | Temp | RH% |
|------------|-------|---------------|--------|-------------|------------|------|------|
| Sept 09/19 | 07:42 | Gym | 1 | 0 | 1 | 68.5 | 82.6 |
| | 07:49 | Library | 2 | 0 | 1 | 69.8 | 68.5 |
| | 07:57 | 2nd floor | 3 | 0 | 0 | 70.3 | 73.0 |
| 165 | 09:29 | 1st floor | 4 | 1 | 2 | 72.0 | 71.0 |
| 100 | 09:37 | library | 5 | 0 | 1 | 69.7 | 63.8 |
| | 09:49 | cafeteria | 6 | 1 | 2 | 73.4 | 65.0 |
| | 10:01 | basement | 7 | 0 | 1 | 73.7 | 61.8 |
| | 10:08 | 2nd floor | 8 | 0 | 1 | 73.9 | 65.0 |
| | 10:14 | computer lab | 9 | 0 | 0 | 75.0 | 64.0 |
| | 11:44 | 1st floor | 10 | 1 | 2 | 74.6 | 65.7 |
| | 11:52 | 2nd floor | 11 | 1 | 2 | 74.2 | 66.3 |
| | 11:59 | Room 34 | 12 | 1 | 3 | 74.6 | 61.0 |
| | 12:05 | Computer room | 13 | 0 | 0 | 77.0 | 60.9 |
| | 12:12 | 1st floor | 14 | 1 | 3 | 76.5 | 64.4 |
| | 12:19 | cafeteria | 15 | 1 | 4 | 76.1 | 61.0 |
| | 13:05 | 1st floor | 16 | 1 | 2 | 77.3 | 62.4 |
| | 13:11 | 2nd floor | 17 | 2 | 3 | 78.4 | 65.0 |
| | 13:59 | gym | 18 | 3 | 5 | 79.7 | 66.8 |

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT #

PHOTOS TAKEN

INSPECTION REPORT


Page of

| Date | Time | Location | Sample | 2.5 microns | 10 microns | Temp | RH% |
|---------|-------|----------------|--------|-------------|------------|------|------|
| t 09.19 | 14:07 | Library | 19 | 1 | 3 | 71.0 | 57.9 |
| | 14:13 | 2nd floor | 20 | 1 | 3 | 78.6 | 63.0 |
| | 14:18 | basement | 21 | 1 | 4 | 79.4 | 58.8 |
| | 15:04 | 1st floor | 22 | 2 | 3 | 77.2 | 63.9 |
| | 15:11 | Basement | 23 | 1 | 2 | 74.1 | 62.1 |
| į | 15:19 | Library | 24 | 2 | 2 | 71.5 | 59. |
| | | | 25 | | | | |
| | | - 80- | 26 | | | 1 | |
| | | | 27 | 0 | | | 1 |
| | | | 28 | | | | |
| | -1 | garage and the | 29 | | | | |
| | | *** | 30 | | - | | - |
| | | - 1 | | | | | 1, |
| | + 1 | 2 | | | | | |
| | | | | | | | |
| | | | | | | | |

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.

Standard Sound Level Meter RealTime Graph Time: 2019-9-9 9:18:26



 Start Time:
 09-09-2019,7:41:41


 Maxnum:
 68.70
 09-09-2019,8:10:19

 Minnum:
 51.00
 09-09-2019,8:06:26

Sample Rate: 1.00 Average: 53.05

Gymnasium AM

Standard Sound Level Meter RealTime Graph Time: 2019-9-10 8:17:9



Start Time: 09-09-2019,9:31:33

Maxnum: 76.50 09-09-2019,13:15:01 Minnum: 37.40 09-09-2019,10:16:25

Sample Rate: 1.00 Average: 43.44

Library