

375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • www.mtllab.net

DoB Special Inspection Agency #0230	REPORT #
INSPECTION REPORT	CAMDIES TAVEN

Page

SAMPLES	TAKEN

Project: (Greenacres School		Date: 09/20/19	
Address: 41 Huntington Avenue, Scarsdale NY 10583		Job ID / MU #:		
Client: Park East Construction		Weather: Sunny(AM)		
Inspection '	Tune at the late to	Contractor: Park F	Foot	
Present At S	Type: Noise and Dust Monitoring Site: 7:00AM	Sub-Contractor:	zast	
	7.0012112	CM/Designer:		
General Area: Northern Yard of School Specific Location: Northern Side of school 1st, 2nd floor, Basement				
Last Inspection: Northern Side of school 1st, 2nd floor, Basement Building Code Section:				
·	Drawings:	Damaning Sout Strain	1221	
Reviewed	Submittals			
Approved	Other:		-	
Deficiency:		Resolution:		
Request For Information:				
Request Fo	r Information:			
Non-Confor	mance Report:			
RFI#: Issued RFI#: Answered NCR#: Issued NCR#: Resolved NCR#: Open				
Observation	ns/Notes:			
Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the library, next to the work performed today.				
An Average noise level of 55.26 dB was measured for the day				
Dust Levels within the Perimeter of the school were measured. These Readings can be found in the				
chart on the next page. Daily PM2.5 density = 3.8, PM10 density = 9.3				
Work today included: Excavating dirt (CAT360), Cutting of rebar, Demolition				
Attachment	s/Photos:			
Time on sit	re: 7:00 AM	ime off site: 3:30 P	'M	
Inspected W	ork Satisfactory (Except As Noted): X No:	Re-inspection Req	quired: Work Completed:	
Inspector: E	rald Hysaj Signature:	4/1/1/2	Certification:	

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of $construction \, sequences. \, The \, field \, representative \, is \, not \, responsible \, for \, identifying \, errors \, and \, omissions \, in \, the \, contract \, documents. \, \, Rev. 11/14/17$



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

INSPECTION REPORT

REPORT #

PHOTOS TAKEN

Page of

September

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
20, 201	9 07:38	LIBRARY	1	1	5	62.1	61.0
	07:44	BASEMENT	2	4	12	63.5	64.1
	07:50	1ST FLOOR	3	10	25	65.8	65.3
	08:02	GYM	4	1	4	67.5	64.1
	08:08	CAFETERIA	5	3	7	66.6	63.7
	08:15	2ND FLOOR	6	8	18	68.9	64.4
	09:43	1ST FLOOR	7	3	3	71.1	58.5
	09:49	2ND FLOOR	8	2	11	77.7	61.8
	09:55	CAFETERIA	9	4	7	72.3	59.8
	10:02	BASEMENT	10	4	8	71.4	62.3
	10:09	1ST FLOOR	11	5	11	77.7	54.9
	10:15	2ND FLOOR	12	3	5	74.1	59.1
	12:45	BASEMENT	13	10	23	72.4	57.5
	12:52	1ST FLOOR	14	6	13	72.3	59.1
·	12:56	2ND FLOOR	15	1	3	73.1	62.4
	13:03	LIBRARY	16	1	3	75.9	52.1
	13:09	1ST FLOOR	17	5	12	74.2	60.8
	13:15	2ND FLOOR	18	3	7	73.7	58.8

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.

		375 R
		• TE
		NYC I
(0	MUNIC	
	TESTING LABOR	IATORY, INC.

375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

INSPECTION REPORT

REPORT #

PHOTOS TAKEN

Page of


September

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
20, 2019	14:43	1st floor	19	2	4	75.3	61.3
	14:49	2nd floor	20	3	8	71.4	60.4
	14:52	basement	21	1	6	72.3	59.3
	-1	**			-		7-
		-					
			-	_			

NOTICE PM2.5: 3.8 PM10: 9.3

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.

Standard Sound Level Meter RealTime Graph Time: 2019-9-20 14:39:6




 Start Time:
 20-09-2019,7:49:37

 Maxnum:
 81.10
 20-09-2019,9:33:39

 Minnum:
 43.30
 20-09-2019,7:50:45

Sample Rate: 1.00 Average: 53.26 Library

Standard Sound Level Meter RealTime Graph Time: 2019-9-20 14:34:28



Start Time: 20-09-2019,7:48:57

Maxnum: 89.00 20-09-2019,11:07:54 Minnum: 49.40 20-09-2019,13:46:41

Sample Rate: 1.00 Average: 57.56

Basement Hallway