

375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • <u>www.mtllab.net</u> NYC DoB Special Inspection Agency #0230

Page

of

REPORT #

IPAL INSPECTION REPORT

SAMPLES TAKEN

Project: (Greenac	res Schoo	ol				Date: 09/24	4/19	
Address: 41 Huntington Avenue, Scarsdale NY 10583					Job ID / MU #	# :			
Client: Park East Construction					Weather: Sunny(AM)				
Inspection '	Type: NL	aise and I	Dust Monito		Contract	or: Park F	last		
Present At S	Site: $7 \cdot$	00AM	Just Monito	oring	Sub-Cont		asi		
General Are			d of School		CM/Desig				
	1101		Side of scho						
Last Inspec				01 130, 2110		Code Sectio			
Dents and	Drawing	S:							
Reviewed	Submittals								
Approved Other:									
Deficiency:					Resolutio	00.			
Denerency.					Resolution				
Request For									
Non-Confor	-			NCD	1				
RFI # :	Issued	RFI # :	Answered	NCR # :	Issued	NCR # :	Resolved	NCR # : Open	
Observation									
	•	• •		-				using a sound	
level m	eter. Rea	idings were	e taken in the	library, nex	t to the w	vork perfor	med today.		
An Aver	age noise	e level of 5	4.93 dB was	measured for	or the day	7			
Dust Lev	vels with	in the Perir	neter of the s	chool were 1	neasured	l. These Re	adings can b	be found in	
the chart	on the n	ext page. I	Daily PM2.5 c	lensity $= 1.5$, PM10 c	density $= 3$.	.8		
		1 0	•	•	-	·			
Work too	lay inclu	ded: Excav	vating dirt (C.	AT360), Cu	tting of r	ebar, Demo	olition, movi	ng river rock	
Attachment	r /Photos								
Time on sit		0 AM				2.20 D	Νſ		
			nt Ac Notada			te: 3:30 P		Work Completed	
inspected w	OFK SAUSI	actory (EXCE	ept As Noted): [X No:	Ke-Ins	spection Req		Work Completed:	
Inspector: E	rald Hys	aj	Signa	ture:	407	2	Certification:		
NOTICE: The	field repres	entative is on s	ite solely to observ	e operation of th	e contractor	identified, for t	he work identified	d and it's conformance to	

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

ABORATORY, INC. INSPECTION REPORT

REPORT #
PHOTOS TAKEN

Page

of

	Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
September	24, 2019	08:04	BASEMENT	1	2	4	70.2	69.2
		08:11	LIBRARY	2	1	3	68.3	63.4
		08:17	1ST FLOOR	3	3	5	71.3	71.4
		09:41	BASEMENT	4	2	5	76.3	60.0
		09:47	1ST FLOOR	5	1	2	77.1	63.4
		09:53	2ND FLOOR	6	1	2	77.0	63.9
		10:02	CAFETERIA	7	2	5	74.3	64.5
		10:08	GYM	8	0	0	77.4	68.7
		10:14	1ST FLOOR	9	2	4	72.3	64.1
		11:08	BASEMENT	10	4	11	79.0	56.5
		11:13	1ST FLOOR	11	2	5	73.5	69.2
		11:18	2ND FLOOR	12	1	3	72.8	70.8
		12:44	BASEMENT	13	1	2	73.4	58.0
		12:50	1ST FLOOR	14	2	4	74.9	71.1
		12:56	2ND FLOOR	15	1	3	75.9	72.0
		13:03	CAFETERIA	16	2	4	69.8	62.3
		13:09	1ST FLOOR	17	1	4	78.3	70.8
		13:15	2ND FLOOR	18	2	5	79.4	71.2

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

BORATORY, INC. INSPECTION REPORT

Page


of

D	ate	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
ptember 2	24, 2019	14:13	1ST FLOOR	19	2	6	82.3	63.4
		14:19	BASEMENT	20	0	1	81.7	52.0
-		14:25	LIBRARY	21	0	1	79.8	51.1
-			ā				-	
-			•					
-						×		
_					•	-		
						e		

NOTICE PM2.5: 1.5 PM10: 3.8

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.

Standard Sound Level Meter RealTime Graph Time: 2019-9-24 14:36:56



 Start Time:
 24-09-2019,8:08:29

 Maxnum:
 93.40
 24-09-2019,8:52:59


 Minnum:
 47.00
 24-09-2019,8:08:30

 Sample Rate:
 1.00

 Average:
 57.20

BASEMENT HALLWAY

Standard Sound Level Meter RealTime Graph Time: 2019-9-24 14:32:56



 Start Time:
 24-09-2019,8:13:46

 Maxnum:
 87.00
 24-09-2019,14:12:30

 Minnum:
 46.00
 24-09-2019,13:31:27

 Sample Rate:
 1.00

 Average:
 52.66

LIBRARY