

375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • <u>www.mtllab.net</u> NYC DoB Special Inspection Agency #0230

Page

of

REPORT #

INSPECTION REPORT

SAMPLES TAKEN

Project: Greenacres School Date: 09/27/19						7/19					
Address: 41 Huntington Avenue, Scarsdale NY 10583						Job ID / MU #	‡ :				
Client: Park East Construction							Weather: Suny	(AM)			
Inspection Type: Noise and Dust Monitoring						Contractor: Park East					
Present At Site: 7:00AM					Sub-Contractor:						
General Are			rd of Schoo		CM/Designer:						
Specific Location: Northern Side of school 1st, 2nd floor, Basement											
Last Inspection:					Building Code Section:						
Reviewed	Drawings										
	Submitta	ils									
Approved	Other:	Other:									
Deficiency:					Resoluti	on:					
Request Fo	r Informa	tion		-							
Non-Confor											
RFI # :	Issued	RFI# :	Answered	NCR # :	Issued	NCR # :	Resolved	NCR # : Open			
RF1 # Issued NCR # Issued NCR # Resolved NCR # Open Observations/Notes:											
			construction in	the perime	er offhe	school was	monitored 1	ising a sound			
			taken in the li					using a sound			
An Avera	age noise	level of 5	3.03 dB was i	neasured for	r the day						
Dust Levels within the Perimeter of the school were measured. These Readings can be found in											
the chart on the next page. Daily PM2.5 density = 1.3 , PM10 density = 3.0											
Work today included: Excavating dirt (CAT360), Delivery of 3" stones, removal of soil								oil			
	2		e (,,,	5	,					
Attachment	s/Photos	:									
Time on sit	e: 7:0	0 AM		Т	ime off sit	te: 3:30 P	M				
Inspected Work Satisfactory (Except As Noted): 🗶 No: 📃 Re-inspection Required: 🗌 Work Completed: 🗌											
_					111-	4.5					
Inspector: E	rald Hys	aj	Signa	ture:	All .	1	Certification:				
NOTICE: The	field repres	entative is on	site solely to observ	e operation of the	e contractor	identified, for th	ie work identified	d and it's conformance to			

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

ABORATORY, INC. INSPECTION REPORT

REPORT #				
PHO	TOS TAKEN			

Page

of

	Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
september	27, 2019	07:31	Putnam	1	0	1	61.5	62.8
		07:38	Huntington Avenue	2	1	3	61.9	63.5
		07:45	Sage Terrace	3	3	5	59.7	61.3
		08:20	Library	4	0	1	63.7	69.1
		08:26	1st floor	5	1	3	64.0	78.8
		08:32	2nd floor	6	0	0	64.6	78.0
		09:43	Basement	7	1	3	62.5	53.4
		09:49	1st floor	8	2	5	68.6	76.4
		09:55	2nd floor	9	2	4	64.5	75.2
		10:03	Cafeteria	10	1	3	69.1	71.3
		10:09	Basement	11	1	2	68.2	59.4
		10:15	1st Floor	12	0	1	73.4	53.5
		11:24	Basement	13	1	2	79.0	50.4
		11:31	1st Floor	14	4	6	81.1	59.2
		11:46	2nd Floor	15	2	4	79.8	58.6
		12:03	Library	16	0	1	78.6	52.5
		12:09	Gym	17	1	2	79.2	61.5
		12:15	Cafeteria	18	2	5	77.4	59.5

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

INSPECTION REPORT

Page


of

	Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
September	27, 2019	13:43	BASEMENT	19	5	10	78.8	51.3
		13:49	Tst Floor	20	1	3	78.5	58.7
		13:55	2nd Floor	21	1	4	78.4	56.4
		14:03	Gym	22	1	2	78.3	59.6
		14:09	Cafeteria	23	0	1	79.2	59.9
		14:15	Library	24	1	1	78.7	51.5
						-	4	-
			*** **		-			100
			*					
						-	0	
	<u> </u>				PM2.5 : 1.3	PM10:3	0	

NOTICE F IVI2.5 : 1.3

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying crrors and omissions in the contract documents.

Standard Sound Level Meter RealTime Graph Time: 2019-9-27 14:28:52



 Start Time:
 27-09-2019,7:22:28

 Maxnum:
 76.40
 27-09-2019,10:32:08


 Minnum:
 42.10
 27-09-2019,13:12:29

 Sample Rate:
 1.00

 Average:
 48.86

LIBRARY DATA

Standard Sound Level Meter RealTime Graph Time: 2019-9-27 14:24:40



*all spikes due to classroom noise

 Start Time:
 27-09-2019,7:18:24

 Maxnum:
 88.70
 27-09-2019,12:41:42

 Minnum:
 48.00
 27-09-2019,8:18:25

 Sample Rate:
 1.00

 Average:
 57.22

BASEMENT HALLWAY