

375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • www.mtllab.ne: NYC DoB Special Inspection Agency #0230

INSPECTION REPORT

t	REPORT #
	82
	SAMPLES TAKEN

Page of

Project: GREENACRES ELEMENTARY SCHOOL						Date: 01/14/2020					
Address: 41 HUNTINGTON AVENUE, SCAR				SDALE	ENY	Job ID / MU #:					
Client: PARK EAST CONSTRUCTION						Weather: CLOUDY					
Inspection '	Type: 3 to	NOT AND		ONTEOD	Contract	or					
Inspection Type: NOISE AND DUST MONITOR Present At Site: 7:00AM					Sub-Contractor:						
		JAWI			CM/Designer:						
General Area: Specific Location:						CM/Designer:					
Last Inspec					Building Code Section:						
Last Hispec		c.		<u></u>	Building Code Section.						
Reviewed		Drawings:									
Approved	Other:	Submittals									
	ouler:	Other:									
Deficiency:					Resoluti	on:					
					÷						
Request For	r Informat	ion:		- 99	0.5						
Non-Confor	mance Re	port:						n			
RFI#:	RFI # : Issued RFI # : Answered NCR # : Issued NCR # : Resolved NCR # : Open										
Observation	ns/Notes:										
Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction) next to the work performed today.											
An average noise levels 46.07 db was measured for the day.											
Dust levels within the perimeter of the school were measured. These readings can be found in the chart on the next page. Daily PM2.5 Density = 3.1 , PM10 Density = 6.7											
Work today included: Cutting rebar with 2-cycle saw, cement mixer running (mortar), deliveries of 3" river rock (dump truck), adjusting steel columns, cutting steel studs, installing and cutting of red brick, Cold Formed Framing above new MPR room, roofers installing copper flashing, Steer All running + excavator, Insulation hose being installed in the attic.											
Attachment	s/Photos	:									
Time on sit	e: 7:00	AM		T	ime off si	te: 3:30P	PM				
Inspected W	ork Satisf	actory (Exce	pt As Noted): [X No:	Re-ins	spection Rec	quired:	Work Completed:			
Inspector: _ERALD HYSAJ Signature: Certification:											

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT #

82

PHOTOS TAKEN

INSPECTION REPORT

Page of

Date	Time	Location	Sample	2.5 microns	10 microns	Temp RH%
A STATE OF THE STA	08:23	GYMNASIUM	1	2	5	68.0 39.0
01.11	08:29	BASEMENT	2	1	3	67.1 43.0
	08:35	1ST FLOOR	3	1	2	67.1 48.2
	09:43	2ND FLOOR	4	2	4	67.6 46.9
	09:49	BASEMENT	5	1	3	66.6 48.0
	09:55	1ST FLOOR	6	2	4	68.0 47.4
	10:01	2ND FLOOR	7	1	2	67.2 48.2
	10:08	1ST FLOOR	8	3	5	68.1 47.5
	10:14	2ND FLOOR	9	4	8	67.0 46.5
	11:43	BASEMENT	10	5	12	65.0 46.9
	11:49	1ST FLOOR	11	6	12	64.8 45.9
	11:55	2ND FLOOR	12	4	10	65.1 44.7
	12:02	BASEMENT	13	5	11	65.4 41.8
	12:08	1ST FLOOR	14	2	5	64.3 40.9
	12:15	2ND FLOOR	15	6	11	64.0 40.0
	13:43	BASEMENT	16	5	12	62.0 40.8
	13:49	1ST FLOOR	17	7	14	63.0 42.5
	13:55	2ND FLOOR	18	4	8	63.0 43.1

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT #

82

PHOTOS TAKEN

INSPECTION REPORT


Page of

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
01.14	14:01	BASEMENT	19	1	3	65.2	44.2
	14:08	1ST FLOOR	20	2	5	64.8	44.5
	14:14	2ND FLOOR	21	1	2	64.4	43.8
						-	
į.							-
-			4				
-			4			-	-
ļ .							
			-				
-			1	-		1	\vdash
			1				
-			+				-

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.


Standard Sound Level Meter RealTime Graph Time: 2020-1-14 14:56:33



Start Time: 14-01-2020,8:14:17 Maxnum: 87.20 14-01-2020,9:54:30 Minnum: 49.50 14-01-2020,12:24:43

Sample Rate: 1.00 Average: 50.64 2nd floor storage

Standard Sound Level Meter RealTime Graph Time: 2020-1-14 14:54:0



Start Time: 14-01-2020,8:18:09

Maxnum: 83.70 14-01-2020,11:52:22 Minnum: 33.20 14-01-2020,9:56:32

Sample Rate: 1.00 Average: 41.50 basement hallway