

375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

INSPECTION RI	EPORT
---------------	-------

Page of

Project:	GREENACRES ELEMENTARY SCHO	OOL	Date: 01/06/2019				
Address:	41 HUNTINGTON AVENUE, SCARSDA	ALE NY	Job ID / MU #:				
Client:	PARK EAST CONSTRUCTION		Weather:				
ai.	Inspection Type: NOISE AND DUST MONITORING Contractor:						
Present At		Sub-Contractor:					
General Are	500 c 2 m 2	CM/Designer:					
Specific Loc	cation: NORTHERN SIDE OF THE SCHO	OL BASEMENT, 1	ST FLOOR, 2ND FLOOR				
Last Inspec	ction:	Building Code Section	n:				
Reviewed	Drawings:						
Approved	Submittals						
Approved	Other:						
Deficiency:		Resolution:					
Deficiency:		Resolution:					
Request Fo	r Information:						
Non-Confor	rmance Report:						
RFI # :	Issued RFI#: Answered NCR#:	Issued NCR # :	Resolved NCR # : Open				
Observation	ns/Notes:	•					
Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction) next to the work performed today.  An average noise level of 50.81 db was measured for the day.  Dust levels within the perimeter of the school were measured. These readings can be found in the chart on the next page. Daily PM2.5 Density = 4.3, PM10 Density = 9.5  Work today included: CUTTING BRICK, EXCAVATOR RUNNING (3" MINUMUM STONE), DELIVER OF 3" STONE + 3/4" RIVER ROCK.							
Attachment	te /Photos		1				
		2.2073					
Time on sit		Time off site: 3:30PN					
Inspected Work Satisfactory (Except As Noted): X No: Re-inspection Required: Work Completed:							
Inspector:	Erald Hysaj Signature:		Certification:				

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



## 375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT #

PHOTOS TAKEN

# **INSPECTION REPORT**

Page of

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
01/06	8:16	BASEMENT	1	2	4	68.7	35.1
	8:22	1ST FLOOR	2	3	6	67.2	52.0
	8:28	2ND FLOOR	3	4	10	67.8	51.2
	9:43	BASEMENT	4	5	10	59.8	36.2
	9:49	1ST FLOOR	5	4	11	59.2	50.2
	9:56	2ND FLOOR	6	2	4	60.4	51.2
	10:05	BASEMENT	7	0	0	58.1	37.2
	10:12	1ST FLOOR	8	4	7	57.8	51.8
	10:18	2ND FLOOR	9	5	8	60.0	51.0
	11:43	BASEMENT	10	8	16	56.4	37.0
	11:49	1ST FLOOR	11	5	12	57.1	50.2
	11:55	2ND FLOOR	12	7	17	55.0	50.8
	12:01	BASEMENT	13	10	21	56.1	37.1
	12:08	1ST FLOOR	14	5	11	57.2	50.5
	12:14	2ND FLOOR	15	8	21	55.7	50.0
	13:43	BASEMENT	16	7	17	56.2	38.1
	13:49	1ST FLOOR	17	3	6	57.3	49.8
	13:55	2ND FLOOR	18	2	4	58.0	47.2

#### NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.

		375 R
		• TE
		NYC D
6	MUNI TESTING LAB	CIPAL IORATORY, INC.

## 375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT #	

PHOTOS TAKEN

**INSPECTION REPORT** 


Page of

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
01/06	14:10	BASEMENT	19	3	6	57.2	39.2
	14:16	1ST FLOOR 2ND FLOOR	20	2	4	58.1	48.1
	14:23	2ND FLOOR	21	2	5	56.7	49.0
<b></b>							

#### NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.

### Standard Sound Level Meter RealTime Graph Time: 2020-1-6 14:53:8



 Start Time:
 06-01-2020,07:59:28

 Maxnum:
 74.10
 06-01-2020,14:14:58

 Minnum:
 49.90
 06-01-2020,11:26:25

Sample Rate: 1.00 Average: 50.81 **BASEMENT HALLWAY**