

375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

INSPECTION REPORT

REPORT #
78

Page of

	PROTOTOLOGY CONTRACTOR AND ALSO	
c	SAMPLES	TAKEN
_ C	Orn-II DEG	

Project:	GREENACRES ELEMENTARY SCHOOL					Date: 01/08/2020			
Address:	41 HUNTINGTON AVENUE, SCARSDAL				ENY	Job ID / N	MU #:		
1 6360	PARK EAST CONSTRUCTION						Weather:	SUNNY	
Inspection'	Inspection Type: NOISE AND DUST MONITORING Contractor:								
Present At S				11010110	Sub-Cont				
General Are	(24) (20)(1)				CM/Desig				
	PHE P. 2003	ORTHERN S	SIDE OF T			**CONTENT	ST FLOO	OR, 2ND FLOOR	
Last Inspec						Code Section			
Reviewed	Drawing	s:		-					
Approved	Submitta	als							
Approved	Other:								
Deficiency:					Resolutio	nn:			
Deficiency.					resolution	ו••			
D	. T. C.								
Request For									
Non-Confor	_			NGD #	, ,	NGD "		NOD#	
RFI # :	Issued		Answered	NCR # :	Issued	NCR # :	Resolve	red NCR # : Open	
Observation	ns/Notes:								
Noise caus	sed by or	ngoing const	ruction in t	he perimete	r of the s	chool was	monitore	ed using a sound	
		ngs were take	en in the ba	sement hall	way (20	feet from	construct	tion) next to the work	
performed	today.								
A m. azzama =	An average noise level of 47.38 db was measured for the day.								
An averag	e noise i	evel 01 4/.38	o uo was m	easured for	me day.				
Dust level	s within	the perimete	r of the sch	ool were m	easured	These read	dings can	be found in the chart	
		Daily PM2.5					65 0411	. of round in the chart	
	1 3	J		, :== : =	5				
Work today included: Cutting brick and CMU, Excavation of soil and stone, Delivery/cutting/									
installation of steel.									
Attachment	e /Photos	•							
						2.200))		
Time on sit	510,40	00AM	A - N - 12 [ime off sit			1411-C11	
inspected W	ork Satisf	actory (Except	As Noted): [X No:	Ke-ins	pection Rec	quired: [Work Completed:	
Inonosta	Inspector: <u>Erald Hysaj</u> Signature: <u>Certification:</u>								
mspector:	<u> craid</u> H	ıysaj	signa	iture:			сегипсац	1011:	

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT #

PHOTOS TAKEN

INSPECTION REPORT

Page of

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
01.08	08:02	SAGE TERRACE	1	0	0	40.2	40.0
01.00	08:12	HUNTINGTON AVE	2	1	3	39.8	39.2
	08:20	PUTNAM ROAD	3	0	1	40.7	40.5
	09:43	BASEMENT	4	2	4	67.8	38.9
	09:49	1ST FLOOR	5	1	2	68.3	39.9
	09:55	2ND FLOOR	6	3	6	66.3	37.5
	10:01	BASEMENT	7	0	0	62.4	38.6
	10:07	1ST FLOOR	8	2	5	63.1	39.3
	10:15	2ND FLOOR	9	4	10	62.9	38.5
	11:43	BASEMENT	10	6	13	61.4	37.5
	11:49	1ST FLOOR	11	4	8	62.0	38.0
	11:56	2ND FLOOR	12	5	9	62.3	37.0
	12:02	BASEMENT	13	7	20	61.2	38.1
	12:09	1ST FLOOR	14	4	7	61.0	37.5
	12:16	2ND FLOOR	15	2	5	60.2	36.2
	13:43	BASEMENT	16	0	2	61.3	38.3
	13:49	1ST FLOOR	17	2	4	62.0	39.1
	13:55	2ND FLOOR	18	1	2	62.1	38.1

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT #					

PHOTOS TAKEN

INSPECTION REPORT


Page	of

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
01.08	14:03	BASEMENT	19	3	7	61.2	40.0
	14:09	1ST FLOOR	20	2	4	62.1	40.1
	14:16	2ND FLOOR	21	5	11	60.2	38.4
		•					

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.

Standard Sound Level Meter RealTime Graph Time: 2020-1-8 14:36:18




Start Time: 08-01-2019,8:04:11

Maxnum: 88.80 08-01-2020,12:31:09 Minnum: 50.90 08-01-2020,09:15:42

Sample Rate: 1.00 Average: 51.28 **BASEMENT HALLWAY**

Standard Sound Level Meter RealTime Graph Time: 2020-01-8 14:42:51



Start Time: 08-01-2020,9:07:12

Maxnum: 81.20 08-01-2020,10:22:03 Minnum: 32.40 08-01-2020,11:13:21

Sample Rate: 1.00 Average: 43.49

2ND FLOOR STORAGE