

375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • <u>www.mtllab.net</u> NYC DoB Special Inspection Agency #0230

REPORT #

79

Page

of

INSPECTION REPORT

SAMPLES TAKEN

Project: GREENACRES ELEMENTARY SCHOOL					Date: 01/09/2019			
Address: 41 HUNTINGTON AVENUE, SCARS					Job ID / MU #:			
Client: PARK EAST CONSTRUCTION					Weather: SUNNY			
Increation '	Timera			Contractory				
Inspection Descent At (UST REPORT	Contractor:				
Present At S	1.0	DOAM		Sub-Contractor:				
General Area: CM/Designer:								
Specific Location: NORTHERN SIDE OF THE SCHOOL BASEMENT, 1ST FLOOR, 2ND FLOOR								
Last Inspec				Building Code Section:				
Reviewed	-	Drawings:						
Approved	2.505	Submittals						
. Fr	Other:							
Deficiency:				Resolution:				
Request For	r Informa	ation:						
Non-Confor								
RFI # :	Issued		swered NCR # :	Issued NCR # :	Resolved NCR # : Open			
Observations/Notes:								
00000114400								
Noigo ag	ugod bu	ongoing constr	nation in the norim	ator of the school w	was monitored using a sound			
	•		-		vas monitored using a sound m construction) next to the			
work per		-	II III the Dasement II	anway (20 leet 110	in construction) next to the			
	loimeu	today.						
An avera	ige noise	e level of 46.40	db was measured for	or the day.				
	.8							
Dust leve	els withi	in the perimeter	of the school were	measured. These r	readings can be found in the			
chart on the next page. Daily PM2.5 Density= 3.0, PM10 Density= 6.0								
Work too	day inclu	uded: cutting br	ick and CMU, Exca	avation of soil and	stone, Delivery/cutting/			
installation of steel.								
Attachments/Photos:								
Time on site: 7:00am Time off site: 3:30pm								
Inspected W	Inspected Work Satisfactory (Except As Noted): X No: Re-inspection Required: Work Completed:							
	/ MA							
Inspector:	Inspector: Erald Hysaj Signature: Certification:							
				' ()				

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

<u>INSPECTION REPORT</u>

REPORT #
79
PHOTOS TAKEN

Page

of

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
01.09	8:14	BASEMENT	1	1	3	68.1	30.1
	8:19	1ST FLOOR	2	2	5	69.2	29.5
	8:25	2ND FLOOR	3	1	2	69.8	30.0
	9:43	BASEMENT	4	0	0	67.3	28.7
	9:49	1ST FLOOR	5	1	1	67.0	28.2
	9:55	2ND FLOOR	6	2	4	66.2	27.7
	10:01	BASEMENT	7	3	6	65.8	26.1
	10:07	1ST FLOOR	8	5	11	62.1	25.1
	10:13	2ND FLOOR	9	4	9	61.8	25.5
	11:43	BASEMENT	10	7	13	61.0	22.4
	11:49	1ST FLOOR	11	3	8	60.8	22.8
	11:55	2ND FLOOR	12	4	8	60.2	22.0
	12:01	BASEMENT	13	3	5	58.0	21.5
	12:07	1ST FLOOR	14	2	4	58.1	23.1
	12:13	2ND FLOOR	15	5	10	57.2	24.2
	13:43	BASEMENT	16	4	7	54.3	25.0
	13:49	1ST FLOOR	17	6	11	55.8	24.1
	13:55	2ND FLOOR	18	2	4	56.1	24.0

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

INSPECTION REPORT

RI	EPORT #	
	79	
PHO	TOS TAKEN	

Page


of

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
01.09		BASEMENT	19	2	5	58.1	24.3
	14:07	1ST FLOOR	20	4	7	57.0	24.9
	14:15	2ND FLOOR	21	2	4	55.0	25.2
							ļ
							ļ
						-	

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.

Standard Sound Level Meter RealTime Graph Time: 2020-1-9 14:43:47



 Start Time:
 09-01-2020,8:32:56

 Maxnum:
 85.60
 09-01-2020,9:52:00


 Minnum:
 34.00
 09-01-2020,9:35:16

 Sample Rate:
 1.00

 Average:
 42.57

BASEMENT HALLWAY

Standard Sound Level Meter RealTime Graph Time: 2020-1-9 14:51:34



 Start Time:
 09-01-2020,8:36:17

 Maxnum:
 81.10
 09-01-2020,15:21:45

 Minnum:
 49.10
 09-01-2020,13:11:22

 Sample Rate:
 1.00

 Average:
 50.30

2nd floor storage closet