

**Greenacres School** 

## 375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

IN	ISE	FC	ΓIΩ	NR	FP	ORT
IГ	чJг		IIV	1A 17		

REPORT #
SAMPLES TAKEN

Page

SAMPLES	TAKEN

Project: Greenacres School							DATE: 10/25/19		
Address: 41 Huntington Avenue, Scarsdale NY 10583						JOB ID: #39			
Client: Park East Construction					WEATHER: SUNNY				
Inspection '	Type: NL	siaa and D	ust Monito		Contract	or: Park E	act .		
Present At S	Site: 7:	oise and D	ust Monne	ring	Sub-Con		asi		
General Are			d of School		CM/Desig				
	1101		de of scho						
Last Inspec		ormem S	ide of scho	01 1St, ZHC		Code Sectio		=	
	Drawing	 S:			8				
Reviewed	Submitta								
Approved	Other:								
Deficiency:					Resolution	on:			
Request Fo	r Informat	ion:							
Non-Confor	mance Re	port:							
RFI # :	Issued	RFI # :	Answered	NCR#:	Issued	NCR # :	Resolved	NCR # : Open	
Observation	ns/Notes:								
work j An Av Dust I the ch	Reading performe werage no Levels with art on the	gs were taked today.  Sise level of thin the Perence next page.	n in the base 52.1 dB was imeter of the Daily PM2.	ement hallway s measured to e school were description of the s	for the date measure 3.0, PM	et from con y red. These	estruction), n	n be found in	
Attachment									
Time on sit		0 AM				te: 3:30 P			
nspected W			ot As Noted): [ Signa		Re-ins	spection Req	uired: Certification:	Work Completed:	

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



1ST FLOOR

2ND FLOOR

14:06

14:12

## 375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT #

PHOTOS TAKEN

62.3

63.1

75.1

76.0

**INSPECTION REPORT** 

Page of

	Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
October	24 ,2019	08:20	BASEMENT	1	0	1	68.9	47.8
		08:26	1ST FLOOR	2	2	5	69.1	48.6
		08:32	2ND FLOOR	3	3	6	69.0	47.5
		09:43	BASEMENT	4	2	4	70.3	50.3
		09:49	1ST FLOOR	5	9	21	68.1	56.3
		09:55	GYMNASIUM	6	9	19	70.2	64.0
		10:00	2ND FLOOR STORAGE	7	4	6	73.2	53.1
		10:06	CAFETERIA	8	4	7	72.0	51.5
		10:12	GYMNASIUM	9	3	5	73.8	56.0
		11:43	BASEMENT	10	1	2	74.0	55.5
		11:50	1ST FLOOR	11	9	19	75.1	59.4
		11:55	2ND FLOOR	12	5	9	76.2	60.3
		12:00	2ND FLOOR STORAGE	13	2	3	74.0	55.1
		12:06	GYMNASIUM	14	1	1	73.4	66.1
		12:12	BASEMENT	15	2	4	75.1	58.1
		13:43	1ST FLOOR	16	1	3	75.4	61.2
		13:49	2ND FLOOR	17	0	0	76.1	60.4
		13:55	2ND FLOOR CLOSET	18	1	2	75.0	55.0
	-	14:00	BASEMENT	19	3	7	77.1	59.1


## NOTICE

20

2

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.

## Standard Sound Level Meter RealTime Graph Time: 2019-10-25 14:48:39



Start Time: 02-10-2019,8:18:59

Maxnum: 90.50 25-10-2019,13:48:18 Minnum: 41.30 25-10-2019,8:03:02

Sample Rate: 1.00

Average: 52.1

BASEMENT HALLWAY