

375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • <u>www.mtllab.net</u> NYC DoB Special Inspection Agency #0230

Page

of

REPORT # 50

INSPECTION REPORT

SAMPLES TAKEN

Project: Greenacres School	Date: 11/12/19						
Address: 41 Huntington Avenue, Scarsdale NY	Job ID/ MU#:						
83 Client: Park East Construction	Weather: Rain/Snow						
Inspection Type: Noise and Dust Monitoring Contractor: Park East							
Present At Site: 7:00AM	Sub-Contractor:						
General Area: Northern Yard of School	CM/Designer:						
Specific Location: Northern Side of school 1st, 2nd floor, Basement							
Last Inspection:	Building Code Section:						
Reviewed Drawings:							
Approved Submittals	Submittals						
Other:							
Deficiency:	Resolution:						
Request For Information:							
Non-Conformance Report:							
RFI# : Issued RFI # : Answered NCR # :	Issued NCR # :	Resolved NCR # : Open					
Observations/Notes:							
Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction), next to the work performed today. An Average noise level of 54.69 dB was measured for the day Dust Levels within the Perimeter of the school were measured. These Readings can be found in the chart on the next page. Daily PM2.5 density = 1.8, PM10 density = 4.8 Work today included: Excavating dirt (CAT360), Delivery of 3" stones, installation of steel I-beams							
Attachments/Photos:							
	Time off site: 3:30 P						
Inspected Work Satisfactory (Except As Noted): X No:	Re-inspection Rec	uired: Work Completed: Certification:					

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

INSPECTION REPORT

REPORT #				
PHOTOS TAKEN				


Page

of

	Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
NOVEMBER	12, 2019	08:18	BASEMENT	1	2	5	62.8	48.7
		08:24	1ST FLOOR	2	1	4	62.2	56.9
		08:31	2ND FLOOR	3	3	6	61.6	58.3
		09:43	BASEMENT	4	1	3	67.3	50.9
		09:49	1ST FLOOR	5	3	7	67.9	58.9
		09:55	2ND FLOOR	6	2	5	58.6	59.2
		10:43	BASEMENT	7	1	4	59.8	53.3
		10:49	1ST FLOOR	8	0	0	60.8	59.8
		10:55	2ND FLOOR	9	1	4	61.2	60.2
		11:00	BASEMENT	10	2	6	69.7	54.1
		11:06	1ST FLOOR	11	2	7	61.4	60.0
		11:12	2ND FLOOR	12	1	3	61.2	59.7
		12:00	BASEMENT	13	6	15	68.8	54.3
		12:06	1ST FLOOR	14	2	8	62.0	60.5
		12:12	2ND FLOOR	15	1	1	61.7	60.9
		13:43	BASEMENT	16	2	6	58.2	55.3
		13:49	1ST FLOOR	17	1	2	62.0	61.2
		13:55	2ND FLOOR	18	2	5	62.4	61.8
	-	14:00	BASEMENT	. 19	2	5	61.2	56.3
		14:05	1ST FLOOR	20	1	3	62.4	63.8
		14:12	2ND FLOOR	21	1	1	62.8	64.2

NOTICE


The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.



Start Time:12-11-2019,08:02:56Maxnum:84.7012-11-2019,11:41:29Minnum:53.0012-11-2019,10:05:07Sample Rate:1.00Average:52.11

BASEMENT HALLWAY

Standard Sound Level Meter RealTime Graph Time: 2019-11-12 14:54:43



 Start Time:
 12-11-2019,8:08:15

 Maxnum:
 86.75
 12-11-2019,11:21:40

 Minnum:
 44.91
 12-11-2019,9:38:20

 Sample Rate:
 1.00

 Average:
 57.22

2ND FLOOR STORAGE UNIT