

Inspector:

375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • <u>www.mtllab.net</u> NYC DoB Special Inspection Agency #0230

REPORT	#
6	88

SAMPLES TAKEN

INSPECTION REPORT

						Pag	e of	STATE LES TRICETO
Project: G	REENAC	CRES E	LEMENTARY S	CHOOL			Date:	12/11/2019
			AVENUE, SCARSI		583		Job ID / M	
Client: PAI	RK EAST	CONST	RUCTION				Weather: S	SNOW
Inspection	Туре: NOI	SE AND I	OUST MONITORING		Contract	or:		
Present At					Sub-Con	tractor:		
General Are	ea:				CM/Desig	gner:		
Specific Loc	cation: NC	RTHER	N SIDE OF SCHOO	L BASEME	NT, 1ST, 2	ND FLOOR		
Last Inspec	tion:				Building	Code Section	n:	
Reviewed	Drawing	ζS:						
Approved	Submitta	als						
ripprovou	Other:							
Deficiency:					Resoluti	on:		
Request Fo	r Informa	tion:						
Non-Confo								
RFI#:	Issued	RFI#	: Answered	NCR # :	Issued	NCR # :[Resolved	d NCR # : Open
Observation	ns/Notes:							
	adings w	-	construction in the	•				using a sound level xt to the work
An averag	e noise l	evel of	43.25 dB was m	easured for	the day.			
			meter of the scho //2.5 Density = 1				dings can t	pe found in the chart
			cutting brick, CM orrugated steel.	U block wo	rk, Excav	ation 3" st/	one, Remo	oving form-work,
Attachment								
Time on sit			٦		Time off si			
Inspected W	ork Satisf	actory (I	Except As Noted): [No:	Re-ins	spection Red	quired:	Work Completed:
	ER	ALD HY	SAI)		

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17

Certification: _

Signature:



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC Dob Special Inspection Agency #0230

INSPECTION REPORT

REPORT # 89

PHOTOS TAKEN

of


Page

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
12/11/2019	60:80	BASEMENT	1	2	4	72.0	37.4
	60:80	1ST FLOOR	2	1	1	8.79	46.1
	08:15	2ND FLOOR	3	0	0	68.1	46.4
	09:43	BASEMENT	4	0	0	71.3	37.9
	09:49	1ST FLOOR	2	0	0	68.5	46.0
	93:60	2ND FLOOR	9	1	2	2.89	46.2
	10:01	BASEMENT	2	0	0	71.0	38.2
	10:07	1ST FLOOR	8	0	0	69.1	45.8
	10:13	2ND FLOOR	6	1	2	69.4	45.2
	11:43	BASEMENT	10	5	11	71.0	38.1
	11:49	1ST FLOOR	11	4	13	2.69	44.8
	11:55	2ND FLOOR	12	3	8	70.0	44.9
	12:01	BASEMENT	13	5	11	70.8	38.3
	12:07	1ST FLOOR	14	7	13	6.69	44.1
	12:13	2ND FLOOR	15	3	2	70.2	44.3
	13:43	BASEMENT	16	1	2	68.4	43.4
	13:49	1ST FLOOR	17	0	0	68.7	43.8
	13:55	2ND FLOOR	18	0	1	0.89	42.7
	14:02	BASEMENT	19	0	1	67.4	41.7
	14:08	1ST FLOOR	20	1	\Box	66.1	40.7
	14:19	2ND FLOOR	21	2	4	66.4	41.2

NOTICE

responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field errors and omissions in the contract documents.

Standard Sound Level Meter RealTime Graph Time: 2019-12-11 14:50:12




Start Time: 11-12-2019,8:08:24

Maxnum: 85.20 11-12-2019,11:43:37 Minnum: 34.10 11-12-2019,13:01:21

Sample Rate: 1.00 Average: 44.10

Standard Sound Level Meter RealTime Graph Time: 2019-12-11 14:49:12



Start Time: 11-12-2019,8:02:31

Maxnum: 78.10 11-12-2019,13:17:19 Minnum: 35.10 11-12-2019,12:11:52

Sample Rate: 1.00 Average: 42.39 2nd floor storage closet