



## INSPECTION REPORT

Project: Greenacres Elementary School	Date: 12/06/2019
Address: 41 Huntington Avenue	Job ID / MU #:
Client: Park East Construction	Weather: Cloudy

Inspection Type: Noise and Dust Report	Contractor:
Present At Site:	Sub-Contractor:
General Area:	CM/Designer:
Specific Location: Northern Side of the building basement, 1st floor, 2nd floor	
Last Inspection:	Building Code Section:
Reviewed Approved	Drawings:
	Submittals
	Other:

Deficiency:	Resolution:			
Request For Information:				
Non-Conformance Report:				
RFI # : <input type="checkbox"/> Issued	RFI # : <input type="checkbox"/> Answered	NCR # : <input type="checkbox"/> Issued	NCR # : <input type="checkbox"/> Resolved	NCR # : <input type="checkbox"/> Open
Observations/Notes:				
<p>Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction) next to the work performed today.</p> <p>An average noise level of 49.15 dB was measured fro the day</p> <p>Dust levels within the perimeter of the school were measured. These readings can be found in the chart on the next page. Daily PM2.5 Density = 3.0, PM10 density = 7.3</p> <p>Work today: Laying Brick, Cutting of brick, CMU block work, excavation 3" stone, removing form-work, punching holes through corrugated steel.</p>				
Attachments/Photos :				
Time on site:		Time off site:		

Inspected Work Satisfactory (Except As Noted): ☐ No: ☐ Re-inspection Required: ☐ Work Completed: ☐

Inspector: Erald Hysaj Signature:  Certification: \_\_\_\_\_



375 RABRO DRIVE, HAUPPAUGE NY 11788  
• TEL: (631) 761-5555 • [www.mtllab.net](http://www.mtllab.net)  
NYC DoB Special Inspection Agency #0230

## INSPECTION REPORT

REPORT #


65

PHOTOS TAKEN

Page of

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
12/06/2019	07:43	Gymnasium	1	2	5	55.9	53.2
	07:49	1st floor	2	1	2	61.0	47.6
	07:55	2nd floor	3	3	7	61.1	48.0
	08:00	Basement	4	2	5	56.1	53.7
	08:06	1st floor	5	4	9	61.5	48.2
	08:12	2nd floor	6	6	14	61.9	48.0
	09:43	Basement	7	2	4	56.4	53.1
	09:49	1st floor	8	1	2	61.9	48.7
	09:55	2nd floor	9	3	7	62.1	48.6
	10:00	Basement	10	3	7	57.1	53.4
	10:06	1st floor	11	1	2	62.0	49.3
	10:13	2nd floor	12	3	6	62.4	49.0
	11:43	Basement	13	2	5	57.4	54.7
	11:49	1st floor	14	4	12	63.4	50.3
	11:55	2nd floor	15	3	6	64.1	50.2
	12:01	Basement	16	2	5	58.1	55.1
	12:07	1st floor	17	1	3	63.0	51.0
	12:13	2nd floor	18	3	8	63.4	50.5
	13:43	basement	19	4	12	60.0	54.4
	13:49	1st floor	20	3	7	62.0	50.1
	13:55	2nd floor	21	5	12	61.6	50.3
	14:01	basement	22	4	11	59.5	54.0
	14:08	1st floor	23	7	17	61.0	48.7
	14:15	2nd floor	24	3	7	60.8	48.0


Standard Sound Level Meter RealTime Graph  
Time: 2019-12-6 14:49:18



Start Time: 06-12-2019,8:01:30  
Maxnum: 86.10 06-12-2019,12:25:52  
Minnum: 51.50 06-12-2019,12:27:15  
Sample Rate: 1.00  
Average: 53.19

Basement hallway

Standard Sound Level Meter RealTime Graph  
Time: 2019-12-6 14:52:51



Start Time: 06-12-2019,8:06:15  
Maxnum: 85.90 06-12-2019,10:42:08  
Minnum: 35.50 06-12-2019,11:31:51  
Sample Rate: 1.00  
Average: 45.09

2nd floor storage closet