

375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

DoB Special Inspection Agency #0230		KEPUKI #
Dob special hispection Agency #0230		103
INSPECTION REPORT		
	100	SAMPLES TAKEN

Page of	SAMPLES T.			
rage	OI	59		

Project: G	Project: GREENACRES ELEMENTARY SCHOOL		Date: 02/13/2020		
	Address: 41 HUNTINGTON AVENUE, SCARSDALE NY		Job ID / MU #:		
G11			Weather: RAIN		
Inspection '	Type: NOISE AND DUST MONITOR	Contractor:			
Present At S		Sub-Contractor:			
General Are	ea:	CM/Designer:			
Specific Loc	ation: N AND S BASEMENT 1ST FI	OOR 2ND FLC	OOR		
Last Inspec	Specific Location: N AND S BASEMENT, 1ST FLOOR, 2ND FLOOR Last Inspection: Building Code Section:				
Reviewed	Drawings:				
Approved	Submittals				
Арргочец	Other:				
Deficiency: Resolution:		Resolution:			
Request For	r Information:				
	mance Report:				
RFI#:	Issued RFI # : Answered NCR # :	Issued NCR # :	Resolved NCR # : Open		
Observation	ns/Notes:				
Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction) next to the work performed today. An average noise level of 55.9 db was measured for the day. Dust levels within the perimeter of the school were measured. These readings can be found in the chart on the next page. Daily PM2.5 Density = 6.0, PM10 Density = 11.4					
Attachment	s/Photos:				
Time on sit		ime off site: 3:30p			
	ork Satisfactory (Except As Noted): X No: Straid Hysaj Signature:	Re-inspection Req	uired: Work Completed: Certification:		

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

103

PHOTOS TAKEN


REPORT #

INSPECTION REPORT

Page of

Date	Time	Location	Sample	2.5 microns	10 microns	Temp RH%
			Sample			
02.13	8:13	BASEMENT	1	7	13	63.1 49.7
1 1 2 2	8:18	1ST FLOOR	2	6	11	62.5 50.2
	8:25	2ND FLOOR	3	5	12	61.8 49.9
	09:43	BASEMENT	4	8	15	70.1 51.5
	09:49	1ST FLOOR	5	9	20	70.7 51.8
	09:55	2ND FLOOR	6	7	13	70.7 52.0
	10:02	BASEMENT	7	5	10	71.1 51.6
	10:08	1ST FLOOR	8	2	4	71.4 51.0
82	10:15	2ND FLOOR	9	3	6	70.8 50.5
59	11:43	BASEMENT	10	6	11	71.2 51.0
	11:49	1ST FLOOR	11	9	19	69.5 51.5
	11:55	2ND FLOOR	12	8	14	70.0 51.0
	12:02	BASEMENT	13	7	12	68.9 50.5
	12:08	1ST FLOOR	14	9	15	68.5 50.0
	12:14	2ND FLOOR	15	10	18	67.2 49.8
9	13:43	BASEMENT	16	11	20	68.5 50.5
	13:49	1ST FLOOR	17	5	9	69.0 50.0
	13:55	2ND FLOOR	18	4	7	68.0 49.2
	14:02	BASEMENT	19	2	4	68.2 49.0
	14:08	1ST FLOOR	20	$\overline{2}$	5	67.8 48.2
	14:15	2ND FLOOR	21	$\overline{1}$	1	67.5 47.2

Standard Sound Level Meter RealTime Graph Time: 2020-2-13 14:54:59



Start Time: 13-02-2020,8:13:03

Maxnum: 90.00 13-02-2020,12:33:09 Minnum: 40.90 13-02-2020,11:57:52

Sample Rate: 1.00 Average: 55.88 **BASEMENT HALLWAY**