

## 375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • www.mtllab.ne NYC DoB Special Inspection Agency #0230

INSPECTION REPORT

t	REPORT #
5	104
	SAMPLES TAKEN

Page of

Project: GREENACRES ELEMENTARY SCH	OOL	Date: 02.14.2020								
Address: 41 HUNTINGTON AVENUE, SCAR		Job ID / MU #:								
Client: PARK EAST CONSTRUCTION		Weather: SUNNY								
Inspection Type: NOISE AND DUST REPORT	Contractor:									
Present At Site:	Sub-Contractor:									
General Area:	CM/Designer:									
Specific Location: N AND S BASEMENT, 1ST FLOOR, 2ND FLOOR										
Last Inspection:	Building Code Section:									
Reviewed Drawings:	1									
Submittals										
Approved Other:										
Deficiency:	Resolution:									
Request For Information:										
Non-Conformance Report:										
RFI # : Issued RFI # : Answered NCR # :	Issued NCR # :	Resolved NCR # : Open								
Observations/Notes:	<u> </u>	1								
Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction) next to the work performed today.										
An average noise level of 56.27 db was measured for the day.										
Dust levels within the perimeter of the school were measured. These readings can be found in the chart on the next page. Daily PM2.5 Density = 5.7, PM10 Density = 9.3										
Work today included: cement mixer machine, 2 Lulls running, 2 excavators, cutting duct work										
Attacker auto /Bhatag										
Attachments/Photos: -cutting steel studs Time on site: 7:00am Time off site: 3:30pm										
	Time off site: 3:30									
Inspected Work Satisfactory (Except As Noted): X No: Re-inspection Required: Work Completed:										
Inspector: Erald Hysaj Signature: Certification:										

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



## 375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT #


PHOTOS TAKEN

**INSPECTION REPORT** 

Page of

Date	Time	Location	Cample	2 E migron -	10 microns	Tome	RH%
	030000000000000000000000000000000000000	Location	Sample	2.5 microns		Temp	100000000000000000000000000000000000000
02.14	8:01	BASEMENT	1 1	11	18	61.2	49.1
	8:06	1ST FLOOR	2	9	16	61.2	50.3
	8:13	2ND FLOOR	3	12	17	61.7	53.3
	9:43	BASEMENT	4	9	15	62.1	52.3
	9:49	1ST FLOOR	5	8	14	62.5	51.5
	9:55	2ND FLOOR	6	6	10	62.8	51.0
	10:02	BASEMENT	7	5	9	61.8	49.2
	10:09	1ST FLOOR	8	7	12	61.5	48.5
	10:15	2ND FLOOR	9	8	13	60.9	48.6
	11:43	BASEMENT	10	4	6	61.5	48.0
	11:49	1ST FLOOR	11	7	11	62.0	46.8
	11:55	2ND FLOOR	12	6	10	62.1	46.5
	12:02	BASEMENT	13	9	15	59.8	46.0
	12:08	1ST FLOOR	14	3	5	59.5	45.2
	12:15	2ND FLOOR	15	2	3	59.0	44.9
	13:43	BASEMENT	16	2	4	60.3	45.1
100	13:49	1ST FLOOR	17	1	1	60.8	45.3
	13:55	2ND FLOOR	18	2	3	59.7	45.0
	14:02	BASEMENT	19	3	5	59.2	44.5
	14:08	1ST FLOOR	20	5	7	58.3	44.2
	14:15	2ND FLOOR	21	1	1	57.8	44.0

## Standard Sound Level Meter RealTime Graph Time: 2020-2-14 14:50:54



Start Time: 14-02-2020,8:03:15

Maxnum: 85.50 14-02-2020,13:32:21 Minnum: 50.70 14-02-2020,8:13:15

Sample Rate: 1.00 Average: 56.27 **BASEMENT HALLWAY**