

GREENACRES ELEMENTARY SCHOOL

Project:

375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

DoB Special Inspection Agency #0230	3 · <u>www</u>	/.iiitiiab.net	REPORT #
			108
INSPECTION REPORT		\$	
	В	c	SAMPLES TAKEN

Page of

Date: 02.27.2020

Address: 4	ess: 41 HUNTINGTON AVENUE, SCARSDALE NY				Job ID / MU #:				
Client: PA	nt: PARK EAST CONSTRUCTION					Weather: CLOUDY			
Inspection Type: NOISE AND DUST MONITOR Present At Site:			Sub-Contractor:						
General Area:			CM/Designer:						
	763757	ANDS	RASEMENI	T 1ST FI		** - C (5-1) -	nOR		
Specific Location: N AND S BASEMENT, 1ST FLOOR, 2ND FLOOR Last Inspection: Building Code Section:									
D 1	Drawing	S:							
Reviewed	Submittals								
Approved	Other:								
Deficiency:			Resolution:						
Request Fo	r Informat	ion:							
Non-Conformance Report:									
RFI # :	Issued	RFI#:	Answered	NCR # :	Issued	NCR#:	Resolved	NCR # : Open	
Observations/Notes:									
Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction) next to the work performed today.									
An average noise level of 57.13 db was measured for the day.									
Dust levels within the perimeter of the school were measured. These readings can be found in the chart on the next page. Daily PM2.5 Density= 7.7, Daily PM10 Density= 13.8									
Cutting concrete planks, Lulls, Cement mixer, Concrete Block Cutter, Streetsweeper caused noise today.									
Attachment	s/Photos								
Time on site: 7:00am Time off site: 3:30pm									
Inspected Work Satisfactory (Except As Noted): X No: Re-inspection Required: Work Completed:									
Inspector: ERALD HYSAJ Signature: Certification:									

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT #


PHOTOS TAKEN

INSPECTION REPORT

Page of

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
Date	0.000.000.000		Sample				_
8	08:10	BASEMENT	1 1	7	13	68.2	45.2
	08:16	1ST FLOOR	2	4	7	69.2	44.1
	08:25	2ND FLOOR	3	3	6	69.1	44.5
	09:43	BASEMENT	4	4	8	70.3	43.2
	09:49	1ST FLOOR	5	5	9	70.1	43.8
	09:55	2ND FLOOR	6	6	12	69.8	43.0
	10:02	BASEMENT	7	9	17	68.7	42.1
	10:10	1ST FLOOR	8	10	19	67.5	41.5
82	10:17	2ND FLOOR	9	8	14	68.2	41.9
E9	11:43	BASEMENT	10	7	12	68.9	40.0
	11:49	1ST FLOOR	11	10	17	69.2	39.8
	11:55	2ND FLOOR	12	9	15	69.4	39.5
	12:02	BASEMENT	13	10	18	68.4	39.0
53	12:10	1ST FLOOR	14	11	19	68.0	39.8
	12:17	2ND FLOOR	15	7	12	67.5	40.1
	13:43	BASEMENT	16	11	18	68.4	38.2
	13:49	1ST FLOOR	17	8	16	69.1	37.5
	13:55	2ND FLOOR	18	9	16	69.8	37.0
	14:02	BASEMENT	19	11	19	69.2	37.8
	14:09	1ST FLOOR	20	7	13	69.2	37.5
	14:16	2ND FLOOR	$\overline{21}$	6	10	70.0	38.1

Standard Sound Level Meter RealTime Graph Time: 2020-2-27 14:49:54



BASEMENT HALLWAY

 Start Time:
 27-02-2020,8:04:20

 Maxnum:
 87.40
 27-02-2020,10:31:07

 Minnum:
 55.70
 27-02-2020,10:59:22

Sample Rate: 1.00 Average: 57.13