

375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • <u>www.mtllab.ne</u> NYC DoB Special Inspection Agency #0230

INSPECTION REPORT

t	REPORT #
	110
	SAMPLES TAKEN

Page of

GREENACRES ELEMENTARY SCHOOL 03.02.2020								<u>2.2020 </u>	
Address: 41 HUNTINGTON AVENUE, SCARS					SDALE	NY	Job ID / MU #	# :	
Client: PARK EAST CONSTRUCTION						Weather: SUNNY			
					Contract	or:			
Inspection Type: NOISE AND DUST MONITOR Present At Site:				Sub-Contractor:					
Transfer 1977				CM/Designer:					
Specific Loc	ation: N	ANDSE	RASEMEN	T 1ST FI	OOR	ND FLO	OOR		
Specific Location: N AND S BASEMENT, 1ST FLOOR, 2ND FLOOR Last Inspection: Building Code Section:									
Reviewed	Drawing	s:		31	V:				
Approved	Submitta	als							
Арргочец	Other:								
Deficiency:				Resolution:					
					Ž.				
Request For	r Informa	tion:			- 10 - 10 - 10 - 10 - 10 - 10 - 10 - 10				
Non-Confor									
RFI#:	Issued	RFI#:	Answered	NCR # :	Issued	NCR#:	Resolved	NCR # : Open	
Observation	ns/Notes:						<u> </u>		
Readings v	were take	n in the base		(20 feet fro	m constru			sound level meter. performed today.	
Dust levels	s within t	he perimeter		l were measu	red. Thes	se readings	can be found	in the chart on the	
Cutting co	ncrete pl	anks, 2 Lull	forklifts runn	ing, cement/	mortar/gr	out mixer,	CMU cutter,	Streetsweeper.	
Attachment	s/Photos	:							
Time on sit	e: 7:00	am		T	ime off sit	te: 3:30p	<u>m</u>		
Inspected W			ot As Noted): [Signa	X No:	Re-ins	pection Re	quired:	Work Completed:	

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT #


PHOTOS TAKEN

INSPECTION REPORT

Page of

						-	
Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
03.02	08:11	BASEMENT	1 1	4	7	65.2	38.2
100	08:18	1ST FLOOR	2	5	10	66.1	41.2
	08:25	2ND FLOOR	3	6	11	66.5	41.0
	09:43	BASEMENT	4	7	12	64.8	39.2
	09:49	1ST FLOOR	5	3	5	65.1	41.5
	09:55	2ND FLOOR	6	4	7	64.0	41.9
	10:02	BASEMENT	7	5	9	64.8	38.2
	10:09	1ST FLOOR	8	8	14	65.2	42.6
60	10:16	2ND FLOOR	9	9	16	65.5	43.1
169	11:43	BASEMENT	10	9	15	66.2	39.1
	11:49	1ST FLOOR	11	8	15	65.8	44.1
	11:55	2ND FLOOR	12	6	11	66.8	44.0
	12:02	BASEMENT	13	7	12	67.2	40.2
	12:09	1ST FLOOR	14	11	19	68.0	45.0
	12:16	2ND FLOOR	15	9	17	67.8	44.9
	13:43	BASEMENT	16	8	14	67.1	40.8
	13:49	1ST FLOOR	17	6	10	66.8	46.0
	13:55	2ND FLOOR	18	5	9	66.1	45.1
	14:03	BASEMENT	19	7	12	65.8	39.8
	14:09	1ST FLOOR	20	8	14	65.5	44.2
	14:16	2ND FLOOR	21	8	15	66.3	43.9

Standard Sound Level Meter RealTime Graph Time: 2020-3-2 14:52:31




Start Time: 02-03-2020,8:11:18

Maxnum: 72.50 02-03-2020,11:08:51 Minnum: 51.30 02-03-2020,12:10:13

Sample Rate: 1.00 Average: 53.12

Standard Sound Level Meter RealTime Graph Time: 2020-3-2 14:53:11



Start Time: 03-02-2020,9:15:21

Maxnum: 72.30 03-02-2020,11:54:52 Minnum: 49.70 03-02-2020,10:35:15

Sample Rate: 1.00 Average: 52.11