



| | |
|---|------------------|
| Project: GREENACRES ELEMENTARY SCHOOL | Date: 03.05.2020 |
| Address: 41 HUNTINGTON AVENUE, SCARSDALE NY | Job ID / MU #: |
| Client: PARK EAST CONSTRUCTION | Weather: SUNNY |

| | | | |
|---|------------|------------------------|--|
| Inspection Type: NOISE AND DUST REPORT | | Contractor: | |
| Present At Site: | | Sub-Contractor: | |
| General Area: | | CM/Designer: | |
| Specific Location: N AND S BASEMENT, 1ST FLOOR, 2ND FLOOR | | | |
| Last Inspection: | | Building Code Section: | |
| Reviewed Approved | Drawings: | | |
| | Submittals | | |
| | Other: | | |

| | |
|-------------|-------------|
| Deficiency: | Resolution: |
| | |

| | | | | | |
|---|---|---|---|---------------------------------------|--|
| Request For Information: | | | | | |
| Non-Conformance Report: | | | | | |
| RFI # : <input type="checkbox"/> Issued | RFI # : <input type="checkbox"/> Answered | NCR # : <input type="checkbox"/> Issued | NCR # : <input type="checkbox"/> Resolved | NCR # : <input type="checkbox"/> Open | |

| |
|--|
| Observations/Notes: |
| Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction) next to the work performed today. |
| An average noise level of 57.88 db was measured for the day. |
| Dust levels within the perimeter of the school were measured. These readings can be found in the chart on the chart on the next page. Daily PM2.5 Density = 8.4, Daily PM10 Density= 15.2 |
| Cutting concrete planks, 2 lull forklifts running, cement/mortar/grout mixer, CMU saw. Cutting storefront material |

| | |
|----------------------|-----------------------|
| Attachments/Photos: | |
| Time on site: 7:00am | Time off site: 3:30pm |

Inspected Work Satisfactory (Except As Noted): ☒ No: ☐ Re-inspection Required: ☐ Work Completed: ☐

Inspector: Erald Hysaj Signature:  Certification: _____



MUNICIPAL
TESTING LABORATORY, INC.

375 RABRO DRIVE, HAUPPAUGE NY 11788
• TEL: (631) 761-5555 • www.mtllab.net
NYC DoB Special Inspection Agency #0230

INSPECTION REPORT


REPORT #

PHOTOS TAKEN

Page of


| Date | Time | Location | Sample | 2.5 microns | 10 microns | Temp | RH% |
|-------|-------|-----------|--------|-------------|------------|------|------|
| 03.05 | 08:11 | BASEMENT | 1 | 4 | 7 | 59.5 | 46.0 |
| | 08:16 | 1ST FLOOR | 2 | 6 | 12 | 59.0 | 46.7 |
| | 08:22 | 2ND FLOOR | 3 | 8 | 15 | 59.2 | 47.1 |
| | 09:43 | BASEMENT | 4 | 11 | 20 | 62.1 | 47.8 |
| | 09:49 | 1ST FLOOR | 5 | 12 | 23 | 61.8 | 48.2 |
| | 09:55 | 2ND FLOOR | 6 | 9 | 17 | 62.3 | 48.8 |
| | 10:02 | BASEMENT | 7 | 8 | 14 | 63.0 | 49.2 |
| | 10:08 | 1ST FLOOR | 8 | 8 | 15 | 62.8 | 48.7 |
| | 10:15 | 2ND FLOOR | 9 | 7 | 12 | 63.5 | 49.1 |
| | 11:43 | BASEMENT | 10 | 8 | 15 | 64.2 | 48.7 |
| | 11:49 | 1ST FLOOR | 11 | 9 | 16 | 65.0 | 48.2 |
| | 11:55 | 2ND FLOOR | 12 | 8 | 14 | 65.2 | 47.2 |
| | 12:02 | BASEMENT | 13 | 7 | 12 | 66.1 | 48.0 |
| | 12:09 | 1ST FLOOR | 14 | 8 | 15 | 65.8 | 47.0 |
| | 12:16 | 2ND FLOOR | 15 | 9 | 17 | 66.3 | 46.2 |
| | 13:43 | BASEMENT | 16 | 12 | 20 | 65.2 | 45.9 |
| | 13:49 | 1ST FLOOR | 17 | 5 | 9 | 64.8 | 46.0 |
| | 13:55 | 2ND FLOOR | 18 | 12 | 21 | 65.3 | 45.5 |
| | 14:02 | BASEMENT | 19 | 7 | 12 | 65.0 | 45.0 |
| | 14:09 | 1ST FLOOR | 20 | 8 | 14 | 64.1 | 45.2 |
| | 14:16 | 2ND FLOOR | 21 | 11 | 20 | 64.0 | 44.9 |

Standard Sound Level Meter RealTime Graph
Time: 2020-3-5 14:46:28



Start Time: 05-03-2020,08:06:50
Maxnum: 93.90 05-03-2020,11:00:14
Minnum: 55.00 05-03-2020,12:09:26
Sample Rate: 1.00
Average: 58.86

Standard Sound Level Meter RealTime Graph
Time: 2020-3-5 14:50:12



Start Time: 05-03-2020,8:01:01
Maxnum: 82.30 05-03-2020,10:31:01
Minnum: 40.80 05-03-2020,10:12:11
Sample Rate: 1.00
Average: 56.91