

375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • <u>www.mtllab.net</u> NYC DoB Special Inspection Agency #0230

INSPECTION	REPORT
-------------------	--------

REPORT #
SAMPLES TAKEN

Page of

. 10					
Project: (Greenacres School		Date: 09/12/19		
Address: 41 Huntington Avenue, Scarsdale NY 10583			Job ID / MU #:		
Client: P	ark East Construction		Weather: Sunny (AM) Rain (PM		
Inspection	Type: Noise and Dust Monitoring	Contractor: Park I	East		
Present At	Site: 7:00AM	Sub-Contractor:			
General Arc	ea: Northern Yard of School	CM/Designer:			
Specific Lo	cation: Northern Side of school 1st, 2nd	l floor, Basemen	t		
Last Inspec		Building Code Section	on:		
Reviewed	Drawings:				
Approved	Submittals				
Approved	Other:				
Deficiency:		Resolution:			
Paguagt Fa	or Information:				
	rmance Report:				
RFI#:	Issued RFI# : Answered NCR# :	Issued NCR # :	Resolved NCR # : Open		
_		Jissued NCK# .[
Observatio	ns/Notes:				
using a	aused by ongoing construction in the p sound level meter. Readings were take ned today.				
An ave	rage noise level of 49.40 was measured	l today			
	evels within the Perimeter of the school n the chart on the next page.	l were measured.	These Readings can be		
Work to	oday included: Excavating dirt (CAT36	60), Cutting of re	bar		
Attachment	ts/Photos:				
Time on sit	te: 7:00 AM T	ime off site: 3:30 P	ΡΜ		
Inspected W	/ork Satisfactory (Except As Noted): X No:	Re-inspection Rec	quired: Work Completed:		
Inspector E	Erald Hysaj Signature:	Matho.	Certification:		

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT #

PHOTOS TAKEN

INSPECTION REPORT

Page of

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
12/19	7:15	Huntington Avenue	1	4	8	76.3	80.9
es.	7:23	Sage Terrace	2	3	1	77.8	81.3
	7:54	Putnam Road	3	4	9	78.9	81.9
	08:14	Library	4	2	3	78.3	76.0
	08:20	1st floor	5	2	4	77.7	78.1
	08:26	Basement	6	1	3	75.2	70.3
	09:40	Library	7	2	4	73.0	63.4
	09:54	2nd floor	8	2	6	74.5	75.1
	09:59	cafeteria	9	2	5	76.0	70.2
	10:03	1st floor	10	2	3	78.9	75.3
	10:09	2nd loor	11	2	5	79.1	75.8
	10:16	Library	12	1	3	72.0	69.0
4	11:43	Gymnasium	13	0	1	76.6	75.6
	11:50	1st floor	14	5	10	79.5	70.4
	11:58	Basement	15	4	10	79.8	62.3
	12:05	1st floor	16	0	1	76.3	65
	12:13	basement	17	1	4	73.5	62.5
	12:19	1st floor	18	2	3	78.3	68.1

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.

		375 R
		• TE NYC I
(0	MUNIC	PAL
	TESTING LABORA	TORY, INC.

375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT #

PHOTOS TAKEN

INSPECTION REPORT


Page of

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
11 19	13:42	1st floor	19	2	4	79.0	71.8
	13:47	Library	20	1	2	71.0	61.7
	13:53	1st floor	21	1	3	78.2	72.4
	14:36	1st floor	22	1	4	79.2	74.0
	14:42	Library	23	1	3	71.0	62.3
	14:49	Basement	24	1	3	75.0	69.1
					_		
		**					
			30				
				•			

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.

Standard Sound Level Meter RealTime Graph Time: 2019-9-12 15:25:53



 Start Time:
 12-09-2019,8:14:07

 Maxnum:
 73.50
 12-09-2019,8:40:43

 Minnum:
 36.30
 12-09-2019,8:19:04

Sample Rate: 1.00 Average: 49.38

Library data