

375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

INCD	FCTI	ON	REP	TRC
11421		UIN	MEI 4	

	REPORT #
l	SAMPLES TAKEN

		Page	OI C			
Project: (Greenacres School		Date: 09/13/19			
Address:	41 Huntington Avenue, Scarsdale NY	10583	Job ID / MU #:			
Client: Park East Construction			Weather: Sunny (AM)			
Inspection	Tuno N	Contractor: Park E	ost			
Present At	Type: Noise and Dust Monitoring Site: 7:00AM	Sub-Contractor:	ast			
		CM/Designer:				
	Northern Yard of School					
Last Inspec	cation: Northern Side of school 1st, 2nd	Building Code Section				
- Hust Hispee	Drawings:	banding dode because				
Reviewed	Submittals					
Approved	Other:					
Deficiency:		Resolution:				
Request Fo	r Information:					
Non-Confo	rmance Report:					
RFI#:	Issued RFI#: Answered NCR#:	Issued NCR # :	Resolved NCR # : Open			
Observatio	ns/Notes:					
using a perform	aused by ongoing construction in the psound level meter. Readings were takened today. Tage noise level of 50,83 was measured	n in the library, n				
be found	evels within the Perimeter of the schood in the chart on the next page. Oday included: Excavating dirt (CAT36)		·			
Attachment	rs/Photos:					
Time on sit		ime off site: 3:30 PM	M			
Inspected W	ork Satisfactory (Except As Noted): X No:	Re-inspection Requ				
Inspector: E		all to	Certification:			

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT #

PHOTOS TAKEN

INSPECTION REPORT

Page of

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
13/19	06:53	Room 8	1	0	0	67.6	73.2
	06:59	Room 8	2	1	3	68.9	71.2
	07:10	Library	3	0	0	73.0	63.0
	07:16	1st floor	4	0	0	73.0	62.4
	07:23	Basement	5	1	2	72.7	68.2
	07:53	Room 8	6	0	0	69.8	68.3
	08:08	1st floor	7	1	2	71.6	66.1
	08:16	2nd floor	8	2	3	72.5	69.2
	08:24	Basement	9	1	3	72.0	67.2
	09:47	Library	10	1	2	69.3	67.1
	09:53	Cafeteria	11	2	5	71.2	66.2
	09:59	1st Floor	12	0	1	72.5	70.3
	10:06	2nd Floor	13	0	1	71.3	72.4
	10:12	Basement	14	1	3	71.0	65.0
	10:19	Cafeteria	15	4	6	69.3	61.0
	11:44	Putnam Rd	16	2	4	68.9	58.0
	11:50	Huntington Ave	17	3	5	68.3	58.4
	11:55	Sage Terrace	18	2	4	68.0	58.8

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.

		375 R
		• TE NYC I
(0	MUNICI	
	TESTING LABORATO	DRY, INC.

375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT #

PHOTOS TAKEN

INSPECTION REPORT


Page of

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
13/19	12 44	2nd Floor	19	2	4	79.0	71.8
	12:50	Basement	20	1	2	71.0	61.7
	12:57	1st floor	21	1	3	78.2	72.4
	13:06	2nd floor	22	1	4	79.2	71.0
	13:12	gymnasium	23	1	3	71.0	73.3
ij.	13:20	1st floor	24	1	3	75.0	69.1
	14:20	2nd floor	2	3	5	72.3	68.3
	14:26	basement	26	2	4	70.4	67.5
	14:41	Library	27	0	2	71.2	64.6
	-1						
						331.33	
		- 1-47			_		
	-					-	-

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.

Standard Sound Level Meter RealTime Graph Time: 2019-9-13 14:51:19




 Start Time:
 13-09-2019,10:02:49

 Maxnum:
 98.60
 13-09-2019 11:49:58

 Minnum:
 40.90
 13-09-2019,12:12:28

Sample Rate: 1.00 Average: 56.05 Kindergarten

Standard Sound Level Meter RealTime Graph Time: 2019-9-13 14:46:49



 Start Time:
 13-09-2019,7:11:17

 Maxnum:
 92.70
 13-09-2019,9:35:56

 Minnum:
 36.00
 13-09-2019,7:17:11

Sample Rate: 1.00 Average: 46.62 **Library Data**