

### 375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

INSPECTION	REPORT
HIJI LCIION	ILLI OILI

1	REPORT #
1	SAMPLES TAKEN

Page	9 01					
Project: Greenacres School						
Address: 41 Huntington Avenue, Scarsdale NY 10583						
	Weather: Sunny(AM)					
Contractor: D-ul- I	74					
	east					
1						
Building code seedo	111.					
Submittals Other:						
Deficiency: Resolution:						
Issued NCR # :	Resolved NCR # : Open					
	s monitored using a sound					
-	inica today.					
for the day						
measured These Re	eadings can be found in					
0, PM10  density = 4	.8					
alivary of 3" stones	removel of soil					
clively of 5 stolles, i	Temovar of Son					
Time off site: 3:30 P	M					
Re-inspection Req	uired: Work Completed:					
1116.						
	Contractor: Park I Sub-Contractor: CM/Designer: Independent of the Sub-Contractor: CM/Designer: Independent of the Suilding Code Section of the Suilding Code Sec					

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



## 375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

**INSPECTION REPORT** 

REPORT #

PHOTOS TAKEN

Page of

September

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
20, 2015	08:00	BASEMENT	1	1	3	66.2	64.4
	08:06	GYM	2	0	2	67.3	75.4
	08:13	LIBRARY	3	1	4	62.1	61.4
	09:44	BASEMENT	4	3	4	69.8	54.8
	09:51	1ST FLOOR	5	2	4	76.0	77.2
	09:56	2ND FLOOR	6	1	5	77.0	78.8
	10:03	BASEMENT	7	5	15	77.4	53.1
	10:09	1ST FLOOR	8	1	3	77.2	79.7
	10:15	2ND FLOOR	9	2	4	78.3	78.4
	11:44	1ST FLOOR	10	3	5	79.3	63.1
	11:52	2ND FLOOR	11	2	5	78.4	62.8
	11:58	BASEMENT	12	5	10	74.3	54.8
	12:03	1ST FLOOR	13	3	7	75.8	64.8
	12:09	2ND FLOOR	14	2	5	76.2	64.9
	12:15	BASEMENT	15	0	1	73.1	56.2
	13:08	PUTNAM + HUNTINGTON INTERSECTION	16	0	2	80.2	48.6
	13:11	BASEMENT	17	4	8	81.3	47.7
	13:18	2ND FLOOR	18	1	2	81.0	52.5

#### NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.

	375 R
	• TE NYC I
=	
MUNIC TESTING LABORA	

# 375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

**INSPECTION REPORT** 

REPORT #

**PHOTOS TAKEN** 

Page of


September

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
25, 2019	14:06	BASEMENT	19	2	4	78.4	53.8
	14:14	1ST FLOOR	20	1	3	79.8	62.1
	14:20	2ND FLOOR	21	4	5	79.6	59.4
							1
							-
						-	-
	_					4	
		•					
		**************************************					
					V.	+	
		<i>y</i> =					
					-		
					2		
	-						-

NOTICE PM2.5: 2.0 PM10: 4.8

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.

# Standard Sound Level Meter RealTime Graph Time: 2019-9-25 14:22:41




Start Time: 25-09-2019,8:11:46

Maxnum: 86.70 25-09-2019,10:30:01 Minnum: 42.20 25-09-2019,12:03:23

Sample Rate: 1.00 Average: 53.24 **LIBRARY** 

### Standard Sound Level Meter RealTime Graph Time: 2019-9-25 14:19:3



 Start Time:
 25-09-2019,8:07:36

 Maxnum:
 83.30
 25-09-2019,8:12:23

 Minnum:
 52.10
 25-09-2019,8:07:36

Sample Rate: 1.00 Average: 58.09 **BASEMENT HALLWAY**