

Project:

375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • www NYC DoB Special Inspection Agency #0230

INSPECTION REPORT

GREENACRES ELEMENTARY SCHOOL

.mtllab.net	REPORT #
5	83

P

200	of	SAMPLES TAKEN
age	OI	.5

Date: 01/15/2020

Address: 41 HUNTINGTON AVENUE, SCARSDALE NY			NY	Job ID / MU #:					
Client: PARK EAST CONSTRUCTION							Weather: SUNNY		
Inspection	Туре:				Contracto	or:			
Present At	Site:				Sub-Cont	ractor:			
General Are	ea:				CM/Desig	ner:			
Specific Loc	cation: N	ORTHERN B	ASEN	MENT, 1ST	T FLOO	R, 2ND	FLOOR		
Last Inspec	tion:			·	Building Code Section:				
Reviewed	Drawing	S:			***				
Approved	Submitta	als							
Approved	Other:								
Deficiency:					Resolutio	nn:			
Deficiency.	•				Resolutio)11.			
Request Fo		of participated files of the							
Non-Confor	7		-5377b		1 1				
RFI # :	Issued	RFI# : Answ	vered	NCR # :	Issued	NCR# :	Resolved NCR # : Open		
Observation	ns/Notes:				***		335		
Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction) next to the									
work perf		~	arcii ii	i the basein	ciit iiaiivv	uy (20 1 cc	t from construction, next to the		
An averag	ge noise l	evel of db was n	neasure	ed for the da	y.				
Dust level	ls within	the perimeter of	the scl	nool were m	easured	These rea	adings can be found in the char		
		Daily PM.5 Dens					adings can be found in the char		
	1 0	•	•		•				
	•	_		•			ning (mortar), deliveries of 3"		
river rock (Dump Truck), adjusting steel columns, cutting steel studs, installing and cutting of red brick,									
4	52 434	ing above new M	IPR ro	om, roofers	installing	copper fl	ashing.		
Attachment	ts/Photos	:							
Time on sit	/ • \	00am	-		ime off sit	e: 3:30	pm		
Inspected W	nspected Work Satisfactory (Except As Noted): X No: Re-inspection Required: Work Completed:								
nonactor Frold Hyggi Signature (Maria)									
inspector:	spector: <u>Erald Hysaj</u> Signature: <u>Certification:</u>								
MOTICE, The	field repres	antativa ic an cita calab	to obcom	o aparation of the	a abattaataa i	dontified for t	the work identified and it's conformance to		

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of $construction \ sequences. \ The field \ representative \ is \ not \ responsible \ for \ identifying \ errors \ and \ omissions \ in \ the \ contract \ documents. \ \ Rev. 11/14/17$



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT #

PHOTOS TAKEN

INSPECTION REPORT

Page of

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
01.15	08:19	BASEMENT	1	3	7	68.1	38.5
	08:25	1ST FLOOR	2	4	10	69.2	39.3
	08:32	2ND FLOOR	3	3	7	69.5	39.8
	09:43	BASEMENT	4	1	2	68.5	37.5
	09:49	1ST FLOOR	5	2	5	70.1	39.6
	09:55	2ND FLOOR	6	3	8	70.5	39.2
	10:02	BASEMENT	7	5	12	68.1	36.9
	10:08	1ST FLOOR	8	2	4	71.2	40.5
	10:14	2ND FLOOR	9	3	7	71.0	40.9
	11:43	BASEMENT	10	6	15	67.5	37.2
	11:49	1ST FLOOR	11	7	18	71.5	41.2
	11:55	2ND FLOOR	12	9	22	72.0	40.9
	12:02	BASEMENT	13	7	17	68.9	38.0
	12:08	1ST FLOOR	14	8	20	71.8	42.4
	12:14	2ND FLOOR	15	6	16	72.3	41.9
	13:43	BASEMENT	16	4	10	70.1	39.1
	13:49	1ST FLOOR	17	5	10	69.8	40.9
	13:55	2ND FLOOR	18	3	7	69.5	40.6

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.

		375 R
		• TE
	=	NYC D
(0	MUNI TESTING LA	CIPAL BORATORY, INC.

375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT	#	

PHOTOS TAKEN

INSPECTION REPORT


Page of

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
01.15	14:05	BASEMENT	19	3	7	67.9	38.6
01110	14:12	1ST FLOOR	20	2	7	70.6	40.7
	14:19	2ND FLOOR	21	3	6	70.5	40.9
							,,,,
							()
: e-						ļ	
-							
-					-		-
	-		-			-	· · · · · · · · · · · · · · · · · · ·

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.

Standard Sound Level Meter RealTime Graph Time: 2020-1-15 14:56:34



Start Time: 15-01-2020,8:29:18

Maxnum: 82.30 15-01-2020,12:53:37 Minnum: 49.10 15-01-2020,11:12:21

Sample Rate: 1.00 Average: 51.24 2ND FLOOR STORAGE