

INSPECTION REPORT

et	REPORT #			
	SAMPLES TAKEN			

01/30/2020

Page of

Project: GREENACRES ELEMENTARY SCHOOL							Date: 01/30/2020					
Address: 41 HUNTINGTON AVENUE, SCARS						ENY	Job ID / MU #	# :				
Client: PARK EAST CONSTRUCTION					7111	SUNNY						
					Contract	or.						
Present At S	Site N	JISE ANI	D DUST M	ONITOR	Sub-Contractor:							
General Are					CM/Designer:							
						li						
Specific Location: N AND S BASEMENT, 1ST FL Last Inspection:				1, 151 FL	Building Code Section:							
	Drawing	S:			Dantag							
Reviewed	Submittals											
Approved	Other:											
Deficiency:					Resolution:							
Request For Information:												
Non-Conformance Report:												
RFI#:	Issued	RFI#:	Answered	NCR # :	Issued	NCR # :[Resolved	NCR # : Open				
Observation	ns/Notes:											
Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction) next to the work performed today.												
An average noise level of 55.08 db was measured for the day.												
Dust levels within the perimeter of the school were measured. These readings can be found in the chart on the next page.												
Attachment	ts/Photos	:										
Time on sit	te: 7:00	am	_	<u>T</u>	ime off si	te: 3:30	pm					
Inspected W			pt As Noted): [Signa		Re-ins	spection Red	quired: Certification:	Work Completed:				
		- ,			1			·				

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230


REPORT #

PHOTOS TAKEN

INSPECTION REPORT

Page of


							-
te	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
1.30	08:21	BASEMENT	1	8	18	54.7	26.8
	08:27	1ST FLOOR	2	9	21	55.5	32.1
	08:35	2ND FLOOR	3	9	20	52.7	30.2
	09:43	BASEMENT	4	3	6	49.8	31.2
	09:49	1ST FLOOR	5	5	10	52.3	32.5
	09:55	2ND FLOOR	6	11	21	53.7	35.1
	10:02	BASEMENT	7	4	10	54.7	35.2
	10:08	1ST FLOOR	8	2	3	53.0	35.0
	10:12	2ND FLOOR	9	9	20	52.5	33.2
	11:43	BASEMENT	10	2	4	55.2	31.2
	11:49	1ST FLOOR	11	3	6	53.2	34.2
	11:55	2ND FLOOR	12	4	9	54.1	35.0
	12:02	BASEMENT	13	3	5	55.0	35.2
	12:08	1ST FLOOR	14	6	13	55.1	32.5
	12:14	2ND FLOOR	15	5	10	56.0	33.7
	13:43	BASEMENT	16	4	8	57.5	34.5
	13:49	1ST FLOOR	17	2	4	56.2	32.8
	13:55	2ND FLOOR	18	1	2	55.5	35.2
	14:03	BASEMENT	19	4	9	55.2	32.1
	14:09	1ST FLOOR	20	5	12	55.0	37.1
	14:15	2ND FLOOR	21	2	5	56.1	36.2
	14:09	1ST FLOOR	20	5	12	55.0	



Start Time: 30-01-2020,8:21:51

Maxnum: 92.10 30-01-2020,10:49:40 Minnum: 36.60 30-01-2020,14:01:57

Sample Rate: 1.00 Average: 54.95 2nd floor storage



Start Time: 30-01-2020,8:19:01

Maxnum: 85.50 30-01-2020,10:51:16 Minnum: 40.80 30-01-2020,8:29:17

Sample Rate: 1.00 Average: 55.21