

#### 375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • <u>www.mtllab.ne</u> NYC DoB Special Inspection Agency #0230

**INSPECTION REPORT** 

	REPORT #
1	

Page of

SAMPLES	TAKEN
SHMLLES	IAKEN

Project: (	Greenacres School		Date: 10/03/19		
Address: 41 Huntington Avenue, Scarsdale NY 10583  Client: Park East Construction		Job ID / MU #:			
Client: Park East Construction			Weather:Sumy(AM)		
Inspection '	Type: Noise and Dust Monitoring	Contractor: Park I	Fast		
Present At S	Site: 7:00AM	Sub-Contractor:	2431		
General Are		CM/Designer:			
Specific Loc	ration: Northern Side of school 1st, 2nd	l floor. Basemen	t		
Last Inspection: Building Code Section:					
Reviewed	Drawings:				
Approved	Submittals				
прриотеа	Other:				
Deficiency:		Resolution:			
Deficiency: Resolution:  Request For Information:  Non-Conformance Report:  RFI # : Issued RFI # : Answered NCR # : Issued NCR # : Resolved NCR # : Open  Observations/Notes:					
Request Fo	r Information:				
Noise caused by ongoing construction in the perimeter of the school was monitored using a sound					
level meter. Readings were taken in the library, next to the work performed today.					
An Average noise level of 48.5 dB was measured for the day					
Dust Levels within the Perimeter of the school were measured. These Readings can be found in					
the chart	on the next page. Daily PM2.5 density = $2.2$	, PM10 density = 4	.0		
Work today included: Excavating dirt (CAT360), Delivery of 3" stones, removal of soil/forms					
Attachment	s/Photos:				
Time on sit	e: 7:00 AM	ime off site: 3:30 P	PM		
Inspected W	ork Satisfactory (Except As Noted): X No:	Re-inspection Rec	quired: Work Completed:		
Inspector: E	rald Hysaj Signature:	All the	Certification:		

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



#### 375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT #

PHOTOS TAKEN

INSPECTION REPORT

Page of

October

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
r 03,2019	07:44	Basement	1	1	2	64.2	62.3
	07:51	1st floor	2	2	4	65.1	71.3
	07:56	2nd floor	3	1	4	64.8	73.1
	08:03	Library	4	2	4	65.1	61.2
	08:09	Basement	5	3	5	63.8	68.4
	08:16	1st Floor	6	1	4	63.1	71.4
	09:36	Basement	7	1	3	64.4	78.8
	09:43	1st Floor	8	1	2	65.7	84.0
	09:50	2nd Floor	9	2	4	66.9	78.7
	10:43	Basement	10	2	5	66.4	71.3
	10:49	1st Floor	11	3	4	63.2	83.1
	10:55	2nd Floor	12	1	4	64.2	81.5
	11:02	Library	13	2	3	65.3	72.1
	11:08	Basement	14	2	2	67.1	73.4
	11:14	Cafeteria	15	2	5	64.2	69.2
	12:43	Basement	16	2	7	67.5	66.1
	12:49	1st Floor	17	2	5	67.8	70.7
	12:55	2nd Floor	18	2	5	68.5	71.9

#### NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.

		375 F
	<b>7</b> 0.	• TE
	=	NYC I
10	MUNIC	IPAL
	TESTING LABOR	ATORY, INC.

# 375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

**INSPECTION REPORT** 

REPORT #

**PHOTOS TAKEN** 

Page

of


October

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
03, 2019	13:03	BASEMENT	19	0	2	71.5	74.6
	13:09	Tst Floor	20	1	3	72.4	69.4
	13:15	library	21	2	4	71.4	73.1
	14:05	Basement	22	1	5	68.0	69.0
	14:10	1st Floor	23	3	4	69.4	74.8
	14:!5	2nd Floor	24	2	6	68.4	73.4
		7.					
		ndi n		-			
		- 1-7		-	_		
	1	*					
							1

PM2.5: 3.3 PM10: 4.0

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.

#### Standard Sound Level Meter RealTime Graph Time: 2019-10-3 14:25:52




Start Time: 03-10-2019,9:33:09

Maxnum: 82.40 03-10-2019,13:11:29 Minnum: 47.50 03-10-2019,14:07:36

Sample Rate: 1.00 Average: 50.69

### **BASEMENT HALLWAY AM 1**

#### Standard Sound Level Meter RealTime Graph Time: 2019-10-3 14:25:40




 Start Time:
 03-10-2019,8:21:28

 Maxnum:
 100.90 03-10-2019,8:52:28

 Minnum:
 36.30 03-10-2019,9:14:45

Sample Rate: 1.00 Average: 46.27 **BASEMENT HALLWAY AM 1** 

## Standard Sound Level Meter RealTime Graph Time: 2019-10-3 14:23:30




Start Time: 03-10-2019,9:41:09

Maxnum: 80.20 03-10-2019,11:39:52 Minnum: 42.10 03-10-2019,14:12:01

Sample Rate: 1.00 Average: 47.18 Library AM 2

#### Standard Sound Level Meter RealTime Graph Time: 2019-10-3 14:22:35



 Start Time:
 03-10-2019,8:24:10

 Maxnum:
 101.20 03-10-2019,8:55:08

 Minnum:
 37.20 03-10-2019,9:17:26

Sample Rate: 1.00 Average: 46.71 **Library AM Data**