



INSPECTION REPORT

Page of

REPORT #

SAMPLES TAKEN

Project: GREENACRES SCHOOL	Date: OCTOBER 15, 2019
Address: 41 HUNTINGTON AVENUE, SCARSDALE NY 10583	Job ID / MU #:
Client: PARK EAST CONSTRUCTION	Weather: SUNNY

Inspection Type: NOISE AND DUST MONITORING	Contractor: PARK EAST
Present At Site: 7:00 AM	Sub-Contractor:
General Area: NORTHERN YARD OF SCHOOL	CM/Designer:
Specific Location: NORTHERN SIDE OF SCHOOL 1st fl, 2nd fl, BASEMENT	
Last Inspection:	Building Code Section:
Reviewed Approved	Drawings:
	Submittals
	Other:

Deficiency:	Resolution:			
Request For Information:				
Non-Conformance Report:				
RFI # : <input type="checkbox"/> Issued	RFI # : <input type="checkbox"/> Answered	NCR # : <input type="checkbox"/> Issued	NCR # : <input type="checkbox"/> Resolved	NCR # : <input type="checkbox"/> Open
Observations/Notes:				
<p>Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the Basement Hallway (20 feet from construction). Readings were also taken in the second floor storage closet.</p> <p>An Average Noise level of 49.95dB was measured for the day.</p> <p>Dust Levels within the perimeter of the school were measured. These readings can be found in the chart on the next page.</p> <p>Daily PM2.5 Density = 2.0</p> <p>Daily PM10 Density = 4.4</p> <p>Work today included:</p> <ul style="list-style-type: none">- Excavation of dirt- Delivery of 3" stone- Removal of Soil				
Attachments/Photos :				
Time on site: 7:00 AM		Time off site: 3:30 PM		

Inspected Work Satisfactory (Except As Noted): ☒ No: ☐ Re-inspection Required: ☐ Work Completed: ☐

Inspector: ERALD HYSAJ Signature:  Certification: _____

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



375 RABRO DRIVE, HAUPPAUGE NY 11788
 • TEL: (631) 761-5555 • www.mtllab.net
 NYC DoB Special Inspection Agency #0230

INSPECTION REPORT

REPORT #


PHOTOS TAKEN

Page of

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
10/15/19	07:43	PUTNAM ROAD	1	2	3	65.3	41.8
	07:49	HUNTINGTON AVE	2	1	1	64.2	42.3
	07:55	SAGE TERRACE	3	1	3	65.8	43.1
	08:01	GYM	4	1	3	66.2	69.6
	08:06	1ST FLOOR	5	1	2	68.4	60.2
	08:12	2ND FLOOR	6	1	2	69.8	61.3
	09:43	BASEMENT	7	1	3	75.7	46.8
	09:49	1ST FLOOR	8	1	2	74.1	53.4
	09:55	2ND FLOOR	9	3	5	74.1	55.1
	10:00	2ND FLOOR STORAGE	10	2	5	74.3	48.2
	10:06	CAFETERIA	11	2	6	74.0	52.5
	10:12	SAGE TERRACE	12	2	5	72.4	40.2
	11:43	BASEMENT	13	1	2	71.6	41.0
	11:49	GYMNASIUM	14	2	4	71.4	58.0
	11:55	1ST FLOOR	15	8	20	71.8	55.5
	12:00	2ND FLOOR	16	3	7	72.9	57.1
	12:05	2ND FLOOR STORAGE	17	0	0	73.0	40.1
	12:10	PUTNAM ROAD	18	0	0	74.1	40.4

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.



REPORT


PHOTOS TAKEN

Page of

October

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.


Standard Sound Level Meter RealTime Graph
Time: 2019-10-15 14:48:54



Start Time: 15-10-2019,8:02:04
Maxnum: 81.00 15-10-2019,9:51:46
Minnum: 40.50 15-10-2019,9:47:29
Sample Rate: 1.00
Average: 43.98

BASEMENT HALLWAY AM #1


Standard Sound Level Meter RealTime Graph
Time: 2019-10-15 14:49:7



Start Time: 15-10-2019,10:13:16
Maxnum: 86.10 15-10-2019,10:25:21
Minnum: 41.30 15-10-2019,11:57:02
Sample Rate: 1.00
Average: 46.10

BASEMENT HALLWAY #2


Standard Sound Level Meter RealTime Graph
Time: 2019-10-15 14:49:23



Start Time: 15-10-2019,12:26:41
Maxnum: 75.70 15-10-2019,12:34:37
Minnum: 41.00 15-10-2019,13:32:54
Sample Rate: 1.00
Average: 44.18

BASEMENT HALLWAY #3


Standard Sound Level Meter RealTime Graph
Time: 2019-10-15 14:53:12



Start Time: 15-10-2019,8:07:55
Maxnum: 87.40 15-10-2019,8:36:20
Minnum: 39.40 15-10-2019,8:31:24
Sample Rate: 1.00
Average: 57.46

2nd floor storage #1


Standard Sound Level Meter RealTime Graph
Time: 2019-10-15 14:53:26



Start Time: 15-10-2019,10:15:40
Maxnum: 87.40 15-10-2019,11:42:27
Minnum: 39.50 15-10-2019,11:29:20
Sample Rate: 1.00
Average: 53.65

2nd floor storage 2

Standard Sound Level Meter RealTime Graph
Time: 2019-10-15 14:53:42



Start Time: 15-10-2019,12:22:53
Maxnum: 84.70 15-10-2019,12:40:59
Minnum: 53.00 15-10-2019,13:01:47
Sample Rate: 1.00
Average: 54.18

2nd floor storage 3