

375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

INSPECTION REPORT

	REPORT #
l	CANADI EC TAVEN

Page

SAM	PIFS	TAKEN
DUILI	LLLO	LUILLIA

Project: (Project: Greenacres School Date		Date: 10/18/19			
Address: 41 Huntington Avenue, Scarsdale NY 10583			Job ID/ MU#:			
Client: Park East Construction			Weather: Cloudy			
Ingression '	Tuno. 37 d. 15	Contractor D- 1- I	74			
Descent At 0	Type: Noise and Dust Monitoring	Contractor: Park East				
	Present At Site: 7:00AM Sub-Contractor:					
General Are	Troftment Tara of Belleof	CM/Designer:				
Last Inspec	ration: Northern Side of school 1st, 2nd	Building Code Section				
Last Inspec		Building Code Secuc	011;			
Reviewed	Drawings:					
Approved		Submittals				
	Other:					
Deficiency:		Resolution:				
Request For	r Information:					
Non-Confor	on-Conformance Report:					
RFI#:	RFI # : Issued RFI # : Answered NCR # : Issued NCR # : Resolved NCR # : Open					
Observations/Notes:						
Noise	caused by ongoing construction in the perim	neter of the school v	vas monitored using a sound			
level 1	meter. Readings were taken in the basement l	hallwav (20 feet fro	om construction), next to the			
work performed today.						
l '	verage noise level of 48.17 dB was measured	for the day				
l	•	•	Dandings can be found in			
Dust Levels within the Perimeter of the school were measured. These Readings can be found in						
the chart on the next page. Daily PM2.5 density = 1.8, PM10 density = 3.5						
Work	today included: Excavating dirt (CAT360), l	Delivery of 3" stone	es, removal of soil/forms			
Attachment	s/Photos:					
Time on sit	e: 7:00 AM T	ime off site: 3:30 P	PM			
Inspected W	ork Satisfactory (Except As Noted): X No:	Re-inspection Rec	quired: Work Completed:			
Inspector: E	rald Hysaj Signature:	All the	Certification:			

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of $construction\ sequences.\ The\ field\ representative\ is\ not\ responsible\ for\ identifying\ errors\ and\ omissions\ in\ the\ contract\ documents.\ Rev. 11/14/17$



14:12

LIBRARY

375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT #

PHOTOS TAKEN

71.4

51.9

INSPECTION REPORT

Page of


Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
October 18,2	2019 07:43	BASEMENT	1	1	1	66.5	56.8
	07:49	1ST FLOOR	2	0	2	70.8	55.0
	07:55	LIBRARY	3	0	1	66.0	54.6
	08:00	CAFETERIA	4	1	3	65.3	55.1
	08:06	2ND	5	1	2	68.0	59.3
	08:12	2ND FLOOR STORAGE	6	0	0	68.9	53.4
. 50	09:43	BASEMENT	7	0	1	68.2	49.5
8	09:49	CAFETERIA	8	1	2	68.3	58.1
	09:55	1ST FLOOR	9	0	1	68.0	55.6
	10:00	2ND FLOOR	10	1	2	69.3	57.6
	10:06	2ND FLOOR CLOSET	11	0	0	69.6	53.0
	10:12	BASEMENT	12	1	2	69.8	51.7
	11:43	1ST FLOOR	13	0	1	74.5	48.8
	11:49	2ND FLOOR	14	1	2	75.3	56.8
	11:55	2ND FLOOR CLOSET	15	0	1	72.1	50.3
	12:00	GYMNASIUM	16	1	4	72.1	60.0
	12:06	BASEMENT	17	2	3	71.8	48.3
	12:12	LIBRARY	18	1	5	72.1	50.5
•	13:43	BASEMENT	19	1	2	72.4	51.2
	13:49	1ST FLOOR	20	2	3	73.4	52.1
	13:55	2ND FLOOR	21	1	2	73.0	51.9
	14:00	2ND FLOOR STORAGE	22	0	1	72.5 73.8	52.9
	14:06	CAFETERIA	23	2	4	73.8	52.7

NOTICE

24

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.

Standard Sound Level Meter RealTime Graph Time: 2019-10-18 14:47:36




Start Time: 18-10-2019,8:01:08

Maxnum: 85.70 18-10-2019,10:27:03 Minnum: 34.10 18-10-2019,10:40:01

Sample Rate: 1.00 Average: 39.98 **BASEMENT HALLWAY 1**


Standard Sound Level Meter RealTime Graph Time: 2019-10-18 14:47:49



Start Time: 18-10-2019,12:00:07 Maxnum: 77.10 18-10-2019,12:33:14 Minnum: 35.30 18-10-2019,13:59:40

Sample Rate: 1.00 Average: 41.89 **BASEMENT HALLWAY 2**

Standard Sound Level Meter RealTime Graph Time: 2019-10-18 14:52:11




Start Time: 18-10-2019,8:05:43

Maxnum: 86.30 18-10-2019,11:14:42 Minnum: 50.30 18-10-2019,8:15:43

Sample Rate: 1.00 Average: 56.90 LIBRARY 1

Standard Sound Level Meter RealTime Graph Time: 2019-10-18 14:52:27



Start Time: 18-10-2019,12:17:00

Maxnum: 71.70 18-10-2019,13:57:28 Minnum: 52.60 18-10-2019,12:47:01

Sample Rate: 1.00 Average: 53.64 LIBRARY 2