

375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • www.mtllab.net REPORT # NYC DoB Special Inspection Agency

#0230	37 11 11 11 11 11 11 11 11 11 11 11 11 11	REPURI	Ħ
#U230		47	

of

Page

SAMPLES TAKEN

INSPECTION REPORT

Project: Greenacres School	Date: 11/06/19					
Address: 41 Huntington Avenue, Scarsdale NY	A .					
Client: Park East Construction	Weather: Cloudy					
Inspection Type: Noise and Dust Monitoring Contractor: Park East						
Inspection Type: Noise and Dust Monitoring Present At Site: 7:00AM	Sub-Contractor:					
, , , , , , , , , , , , , , , , , , , ,	CM/Designer:					
General Area: Northern Yard of School Specific Location: Northern Side of school 1st, 2nd	1					
Last Inspection:	Building Code Section:					
Drawings:						
Submittals	Drawings: Submittals Other: Resolution: It For Information: Issued RFI # : Answered NCR # : Issued NCR # : Resolved NCR # : Open rations/Notes: Drawings: Resolution: Resolution: Other: Other: Resolved NCR # : Open rations/Notes: Other: Other:					
Approved						
Deficiency:	Resolution:					
Request For Information:						
Non-Conformance Report:						
RFI # : Issued RFI # : Answered NCR # :	Issued NCR # : Resolved NCR # : Open					
Observations/Notes:	,					
Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction), next to the work performed today. An Average noise level of 59.14 dB was measured for the day Dust Levels within the Perimeter of the school were measured. These Readings can be found in the chart on the next page. Daily PM2.5 density = 1.6, PM10 density = 3.9 Work today included: Excavating dirt (CAT360), Delivery of 3" stones, installation of steel I-beams						
Attachments/Photos:						
Time on site: 7:00 AM	Time off site: 3:30 PM					
Inspected Work Satisfactory (Except As Noted): X No: Re-inspection Required: Work Completed:						
Drawings: Submittals Other: Pequest For Information: On-Conformance Report: Fit # : Issued RFI # : Answered NCR # : Issued NCR # : Resolved NCR # : Open Open Open Open Open Open Open Open						

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

INSPECTION REPORT

REPORT #

PHOTOS TAKEN

Page of


NOVEMBER

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
06, 2019	08:01	BASEMENT	1	1	3	65.8	46.
	08:07	1ST FLOOR	2	2	5	66.0	48.
13	08:11	2ND FLOOR	3	1	1	66.1	48.
	09:43	BASEMENT	4	2	4	65.9	48.
	09:49	1ST FLOOR	5	2	6	67.0	50.
	09:55	2ND FLOOR	6	1	4	67.3	50.
	10:00	BASEMENT	7	0	0	68.1	49.
	10:06	1ST FLOOR	8	1	1	69.2	50.
	10:12	2ND FLOOR	9	2	4	69.7	50.
	11:43	BASEMENT	10	1	2	68.1	49.
	11:49	1ST FLOOR	11	0	0	70.4	52.
1 1 1	11:55	2ND FLOOR	12	2	5	70.5	53.
	12:00	BASEMENT	13	3	6	68.5	49.
	12:06	1ST FLOOR	14	2	4	71.4	53.
	12:12	2ND FLOOR	15	1	2	71.9	53.
	13:43	BASEMENT	16	4	10	69.2	49.
	13:49	1ST FLOOR	17	2	6	72.3	54.
	13:55	2ND FLOOR	18	1	3	72.9	54.
·	14:00	BASEMENT	19	2	5	69.5	48.
	14:05	1ST FLOOR	20	3	8	73.4	55.
	14:12	2ND FLOOR	21	1	2	73.1	55.

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.


Standard Sound Level Meter RealTime Graph Time: 2019-11-6 14:43:35



Start Time: 06-11-2019,9:17:47 Maxnum: 72.50 06-11-2019,9:24:41 Minnum: 56.90 06-11-2019,9:17:47

Sample Rate: 1.00 Average: 59.13 **BASEMENT HALLWAY 1**

Standard Sound Level Meter RealTime Graph Time: 2019-11-6 14:45:47



 Start Time:
 06-11-2019,11:34:51

 Maxnum:
 82.70 06-11-2019,12:58:44

 Minnum:
 58.70 06-11-2019,12:25:13

Sample Rate: 1.00 Average: 59.14 **BASEMENT HALLWAY 2**