



Project: <b>Greenacres Elementary School</b>	Date: <b>11-07-19</b>
Address: <b>41 Huntington Ave, Scarsdale, NY 10583</b>	Job ID / MU #:
Client: <b>Scarsdale CSD</b>	Weather: <b>Cloudy ~51deg F</b>

Inspection Type: <b>Noise and Dust Monitoring</b>	Contractor: <b>Park East Construction</b>
Present At Site: <b>Don Herlihy</b>	Sub-Contractor:
General Area: <b>North Side of School</b>	CM/Designer:
Specific Location: <b>North side of School in the basement, 1st and 2nd Floor</b>	
Last Inspection:	Building Code Section:
Reviewed Approved	Drawings:
	Submittals
	Other:

Deficiency:	Resolution:			
Request For Information:				
Non-Conformance Report:				
RFI # : <input type="checkbox"/> Issued	RFI # : <input type="checkbox"/> Answered	NCR # : <input type="checkbox"/> Issued	NCR # : <input type="checkbox"/> Resolved	NCR # : <input type="checkbox"/> Open
Observations/Notes:				
<p>On site for the on going monitoring of construction Noise and Dust for Greenacres Elementary School.</p> <p>Noise Monitoring- Readings were taken in the Art room and Library (Basement and 1st Floor) which is closest to the construction zone. Average readings were 53.87 dBa.</p> <p>Note- around 2pm (photo5) the noise meter was exposed to the outside noise due to the window next to meter was opened. Class was in session during this timeframe. During this time the average dBa was about 62 dBa</p> <p>Dust Monitoring- Readings taken are as show on page 2 of this report.</p> <p>Work performed today- Excavation (CAT360), earthwork operations near library and art room.</p>				
Attachments /Photos :				
Time on site: <b>7a</b>		Time off site: <b>330p</b>		

Inspected Work Satisfactory (Except As Noted): ☒ No: ☐ Re-inspection Required: ☐ Work Completed: ☒

Inspector: Sean Donnelly Signature:  Certification: \_\_\_\_\_

**NOTICE:** The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



375 RABRO DRIVE, HAUPPAUGE NY 11788  
• TEL: (631) 761-5555 • www.mtllab.net  
NYC DoB Special Inspection Agency #0230

REPORT #  
**SD11719**

PHOTOS TAKEN

## INSPECTION REPORT

Page 2 of 3

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
11-06	730a	North side 2nd and 1st floor hallways	1	2	4	70.9	50.2
	745a	Basement	2	1	3	71.2	51.6
	900a	1st floor	3	1	3	69.8	53.5
	910a	2nd floor	4	2	4	70.1	51.2
	1010a	Basement	5	2	5	71.2	41.8
	1015a	1st Floor	6	3	6	73.9	42.3
	1130a	Basement	7	1	2	75.9	42.8
	1135a	1st Floor	8	2	5	73.8	46.8
	1140a	2nd Floor	9	3	7	79.3	45.3
	115p	Basement	10	1	2	75.4	44.6
	120p	1st floor	11	2	5	80.4	43.0
	125p	2nd floor	12	2	5	83.7	42.2
	220p	1st Floor	13	2	5	80.6	41.9
	225p	2nd Floor	14	1	3	81.3	43.8
	230p	Basement	15	3	8	82.0	41.5

### NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction success. The field representative is not responsible for identifying errors and omissions in the contract documents.



## INSPECTION REPORT

Photo 1



945am-Excavation for footings

1147a-Excavation for footings and removal of water

Photo 2



Inspector: Sean Donnelly Signature:  Certification: \_\_\_\_\_

**NOTICE:** The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17






Photo 3



130pm


209pm- Photo 5 shows window was left open in front of noise meter.

Photos 4,5



Inspector: Sean Donnelly Signature:  Certification: \_\_\_\_\_

**NOTICE:** The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



Start Time: 07-11-2019,11:18:27  
Maxnum: 95.20 07-11-2019,16:03:31  
Minnum: 46.30 07-11-2019,16:00:59  
Sample Rate: 1.00  
Average: 53.87