

375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • www.mtllab.net
NYC DoB Special Inspection Agency #0230

REPORT #

SAMPLES TAKEN

INSPECTION REPORT

Page of

| Address: 41 Huntington Avenue, Scarsdale NY 10583 Client: Park East Construction Inspection Type: Noise and Dust Monitoring Present At Site: 7:00AM General Area: Northern Yard of School Specific Location: Northern Side of school 1st, 2nd floor, Basement Last Inspection: Reviewed Approved Drawings: Submittals Other: Deficiency: Resolution: Request For Information: Non-Conformance Report: RFI#: Issued RFI#: Answered NCR#: Issued NCR#: Resolved NCR#: Open Observations/Notes: Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction), next to the work performed today. An Average noise level of 51.39 dB was measured for the day Dust Levels within the Perimeter of the school were measured. These Readings can be found in the chart on the next page. Daily PM2.5 density = 4.0, PM10 density = 8.1 Work today included: moving of 3" stones, installation of steel I-beams, CMU wall built Attachments/Photos: Time on site: 7:00 AM Time off site: 3:30 PM | Project: Greenacres School | | Date: 11/27/19 | | | | | |
|--|---|--|-----------------------|--|--|--|--|--|
| Inspection Type: Noise and Dust Monitoring Present At Site: 7:00AM General Area: Northern Yard of School Specific Location: Northern Side of school 1st, 2nd floor, Basement Last Inspection: Reviewed Approved Drawings: Submittals Other: Request For Information: Non-Conformance Report: RFI#: Issued RFI#: Answered NCR#: Issued NCR#: Resolved NCR#: Open Observations/Notes: Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction), next to the work performed today. An Average noise level of 51.39 dB was measured for the day Dust Levels within the Perimeter of the school were measured. These Readings can be found in the chart on the next page. Daily PM2.5 density = 4.0, PM10 density = 8.1 Work today included: moving of 3" stones, installation of steel I-beams, CMU wall built Attachments/Photos: Time on site: 7:00 AM Time off site: 3:30 PM Inspector Erald Hysaj Signature: Certification: | Address: 41 Huntington Avenue, Scarsdale NY 10583 | | | | | | | |
| Sub-Contractor: | Client: Park East Construction | | Weather: Sunny | | | | | |
| Sub-Contractor: | Inspection Type: Noise and Dust Monitoring | Contractor: Park E | ast | | | | | |
| Specific Location: Northern Side of school 1st, 2nd floor, Basement Last Inspection: Reviewed Approved Drawings: Submittals Other: Deficiency: Resolution: Resolution: Request For Information: Report: Resolved NCR # : Issued NCR # : Open Observations/Notes: Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction), next to the work performed today. An Average noise level of 51.39 dB was measured for the day Dust Levels within the Perimeter of the school were measured. These Readings can be found in the chart on the next page. Daily PM2.5 density = 4.0, PM10 density = 8.1 Work today included: moving of 3" stones, installation of steel I-beams, CMU wall built Attachments/Photos: Time off site: 3:30 PM Inspector. Erald Hysaj Signature: Gertification: Gertificatio | Present At Site: 7:00AM | | | | | | | |
| Specific Location: Northern Side of school 1st, 2nd floor, Basement | General Area: Northern Yard of School | CM/Designer: | | | | | | |
| Reviewed Approved Drawings: Submittals Other: Deficiency: | | d floor, Basement | | | | | | |
| Submittals Other: Resolution: Request For Information: | Last Inspection: | Building Code Section: | | | | | | |
| Deficiency: Request For Information: Non-Conformance Report: RFI#: Issued RFI#: Answered NCR#: Issued NCR#: Resolved NCR#: Open Observations/Notes: Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction), next to the work performed today. An Average noise level of 51.39 dB was measured for the day Dust Levels within the Perimeter of the school were measured. These Readings can be found in the chart on the next page. Daily PM2.5 density = 4.0, PM10 density = 8.1 Work today included: moving of 3" stones, installation of steel I-beams, CMU wall built Attachments/Photos: Time on site: 7:00 AM Time off site: 3:30 PM Inspected Work Satisfactory (Except As Noted): X No: Re-inspection Required: Work Completed: Inspector Erald Hysaj Signature: Certification: | Reviewed | | | | | | | |
| Deficiency: Request For Information: Non-Conformance Report: RFI#: Issued RFI #: Answered NCR #: Issued NCR #: Resolved NCR #: Open Observations/Notes: Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction), next to the work performed today. An Average noise level of 51.39 dB was measured for the day Dust Levels within the Perimeter of the school were measured. These Readings can be found in the chart on the next page. Daily PM2.5 density = 4.0, PM10 density = 8.1 Work today included: moving of 3" stones, installation of steel I-beams, CMU wall built Attachments/Photos: Time on site: 7:00 AM Time off site: 3:30 PM Inspector Erald Hysaj Signature: Certification: | Approved | | | | | | | |
| Request For Information: Non-Conformance Report: RFI# : | Other: | | | | | | | |
| Non-Conformance Report: RFI#: Issued RFI #: Answered NCR #: Issued NCR #: Resolved NCR #: Open Observations/Notes: Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction), next to the work performed today. An Average noise level of 51.39 dB was measured for the day Dust Levels within the Perimeter of the school were measured. These Readings can be found in the chart on the next page. Daily PM2.5 density = 4.0, PM10 density = 8.1 Work today included: moving of 3" stones, installation of steel I-beams, CMU wall built Attachments/Photos: Time on site: 7:00 AM Time off site: 3:30 PM Inspected Work Satisfactory (Except As Noted): X No: Re-inspection Required: Work Completed: Erald Hysaj Signature: Certification: | Deficiency: | Resolution: | Resolution: | | | | | |
| Non-Conformance Report: RFI#: Issued RFI #: Answered NCR #: Issued NCR #: Resolved NCR #: Open Observations/Notes: Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction), next to the work performed today. An Average noise level of 51.39 dB was measured for the day Dust Levels within the Perimeter of the school were measured. These Readings can be found in the chart on the next page. Daily PM2.5 density = 4.0, PM10 density = 8.1 Work today included: moving of 3" stones, installation of steel I-beams, CMU wall built Attachments/Photos: Time on site: 7:00 AM Time off site: 3:30 PM Inspected Work Satisfactory (Except As Noted): X No: Re-inspection Required: Work Completed: Erald Hysaj Signature: Certification: | | | | | | | | |
| RFI#: Issued RFI#: Answered NCR#: Issued NCR#: Resolved NCR#: Open Observations/Notes: Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction), next to the work performed today. An Average noise level of 51.39 dB was measured for the day Dust Levels within the Perimeter of the school were measured. These Readings can be found in the chart on the next page. Daily PM2.5 density = 4.0, PM10 density = 8.1 Work today included: moving of 3" stones, installation of steel I-beams, CMU wall built Attachments/Photos: Time on site: 7:00 AM Time off site: 3:30 PM Inspected Work Satisfactory (Except As Noted): X No: Re-inspection Required: Work Completed: Certification: | Request For Information: | | | | | | | |
| Observations/Notes: Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction), next to the work performed today. An Average noise level of 51.39 dB was measured for the day Dust Levels within the Perimeter of the school were measured. These Readings can be found in the chart on the next page. Daily PM2.5 density = 4.0, PM10 density = 8.1 Work today included: moving of 3" stones, installation of steel I-beams, CMU wall built Attachments/Photos: Time on site: 7:00 AM Time off site: 3:30 PM Inspected Work Satisfactory (Except As Noted): X No: Re-inspection Required: Work Completed: Inspector Erald Hysaj Signature: Certification: | Non-Conformance Report: | | | | | | | |
| Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction), next to the work performed today. An Average noise level of 51.39 dB was measured for the day Dust Levels within the Perimeter of the school were measured. These Readings can be found in the chart on the next page. Daily PM2.5 density = 4.0, PM10 density = 8.1 Work today included: moving of 3" stones, installation of steel I-beams, CMU wall built Attachments/Photos: Time on site: 7:00 AM Time off site: 3:30 PM Inspected Work Satisfactory (Except As Noted): X No: Re-inspection Required: Work Completed: Inspector Erald Hysaj Signature: Certification: | RFI# : Issued RFI # : Answered NCR # : | Issued NCR # : | Resolved NCR # : Open | | | | | |
| level meter. Readings were taken in the basement hallway (20 feet from construction), next to the work performed today. An Average noise level of 51.39 dB was measured for the day Dust Levels within the Perimeter of the school were measured. These Readings can be found in the chart on the next page. Daily PM2.5 density = 4.0, PM10 density = 8.1 Work today included: moving of 3" stones, installation of steel I-beams, CMU wall built Attachments/Photos: Time on site: 7:00 AM Time off site: 3:30 PM Inspected Work Satisfactory (Except As Noted): X No: Re-inspection Required: Work Completed: Inspector: Erald Hysaj Signature: Certification: | Observations/Notes: | | | | | | | |
| Time on site: 7:00 AM Time off site: 3:30 PM Inspected Work Satisfactory (Except As Noted): X No: Re-inspection Required: Work Completed: Certification: | level meter. Readings were taken in the basement hallway (20 feet from construction), next to the work performed today. An Average noise level of 51.39 dB was measured for the day Dust Levels within the Perimeter of the school were measured. These Readings can be found in the chart on the next page. Daily PM2.5 density = 4.0, PM10 density = 8.1 Work today included: moving of 3" stones, installation of steel I-beams, CMU wall built | | | | | | | |
| Inspected Work Satisfactory (Except As Noted): X No: Re-inspection Required: Work Completed: Inspector: Erald Hysaj Signature: Certification: | | | _ | | | | | |
| Inspector Erald Hysaj Signature: Certification: | | | | | | | | |
| | , | Mts | | | | | | |
| | | The same of the sa | | | | | | |

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



375 RABRO DRIVE, HAUPPAUGE NY 11788
• TEL: (631) 761-5555 • www.mtllab.net
NYC DoB Special Inspection Agency #0230

REPORT #

PHOTOS TAKEN

INSPECTION REPORT


GYMNASIUM was tested periodically throughout the day

| i | | | mas tested per 10 | | agriout ti | - | T | Tana. |
|----------|----------|-------|-------------------|----------|-------------|------------|------|-------|
| | Date | Time | Location | Sample | 2.5 microns | 10 microns | Temp | RH% |
| lovember | 27, 2019 | 08:10 | BASEMENT | 1 | 3 | 6 | 63.5 | 43.5 |
| | | 08:17 | 1ST FLOOR | 2 | 4 | 7 | 65.2 | 55.8 |
| | | 08:23 | 2ND FLOOR | 3 | 2 | 4 | 65.4 | 55.7 |
| | | 09:03 | GYMNASIUM | 4 | 3 | 5 | 64.2 | 62.4 |
| | | 09:09 | GYMNASIUM | 5 | 5 | 10 | 63.9 | 62.0 |
| | | 09:15 | GYMNASIUM | 6 | 1 | 4 | 64.2 | 62.1 |
| | | 10:02 | BASEMENT | 7 | 4 | 9 | 64.8 | 62.0 |
| | - | 10:07 | 1ST FLOOR | 8 | 3 | 7 | 65.1 | 61.8 |
| | | 10:13 | 2ND FLOOR | 9 | 5 | 9 | 65.3 | 61.7 |
| | | 11:43 | BASEMENT | 10 | 2 | 5 | 65.6 | 62.1 |
| - { | | 11:49 | 1ST FLOOR | 11 | 3 | 7 | 64.8 | 62.0 |
| | | 11:55 | 2ND FLOOR | 12 | 5 | 12 | 65.1 | 61.8 |
| | | 12:02 | BASEMENT | 13 | 6 | 10 | 65.0 | 62.1 |
| | | 12:08 | 1ST FLOOR | 14 | 2 | 5 | 64.8 | 61.7 |
| | | 12:14 | 2ND FLOOR | 15 | 1 | 4 | 65.2 | 62.4 |
| | | 13:43 | BASEMENT | 16 | 1 | 2 | 65.0 | 62.2 |
| | | 13:49 | 1ST FLOOR | 17 | 2 | 4 | 66.8 | 61.7 |
| | | 13:55 | 2ND FLOOR | 18 | 3 | 7 | 66.5 | 61.6 |
| | | 14:02 | BASEMENT | 19 | 4 | 9 | 66.0 | 61.0 |
| | | 14:08 | 1ST FLOOR | 20 | 4 | 7 | 65.9 | 62.1 |
| | | 14:13 | 2ND FLOOR | 21 | 3 | 7 | 65.7 | 62.0 |
| | • | 10:19 | Gymnasium | * | 3 | 7 | 65.5 | 62.4 |
| - | | | Gymnasium | * | 4 | 8 | 65.8 | |
| | • | 12:03 | Gymnasium | * NOTICE | 2 | 7 | 65.4 | |

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.

Elevated levels of dust in gymnasium due to school event

Standard Sound Level Meter RealTime Graph Time: 2019-11-27 14:59:40




Start Time: 23-10-2019,8:19:55 Maxnum: 87.40 27-11-2019,8:50:00 Minnum: 47.70 23-11-2019,8:19:55

Sample Rate: 1.00 Average: 55.54

Basement hallway

Standard Sound Level Meter RealTime Graph Time: 2019-11-27 14:59:27



 Start Time:
 23-10-2019,8:25:04

 Maxnum:
 79.00
 27-11-2019,11:15:25

 Minnum:
 35.30
 27-11-2019,12:39:43

Sample Rate: 1.00 Average:

2nd floor storage