

Project:

375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • www.mtlla NYC DoB Special Inspection Agency #0230

INSPECTION REPORT

b.net	REPORT #
	98
	SAMPLES TAKEN

Page of

Date: 02/06/2020

Project: GREENACRES ELEMENTARY SC	Date: 02/06/2020							
Address: 41 HUNTINGTON AVENUE, SCAI	Job ID / MU #:							
Client: PARK EAST CONSTRUCTION	Weather: RAIN							
Inspection Type: NOISE AND DUST MONITO	Contractor:							
Present At Site:	Sub-Contractor:							
General Area:	CM/Designer:	2002 (S)						
Specific Location: N AND S BASEMENT, 1ST FLOOR, 2ND FLOOR								
Last Inspection:		Building Code Section:						
Reviewed Drawings:	Ma							
Submittals	Submittals							
Approved Other:								
Deficiency:	Resolution:	Resolution:						
Request For Information:								
Non-Conformance Report:								
RFI # : Issued RFI # : Answered NCR # :	Issued NCR #	: Resolved NCR # : Oper						
Observations/Notes:								
Noise caused by ongoing construction in the	nerimeter of the	school was monitored using						
Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from								
construction) next to the work performed today.								
construction, heat to the work performed today.								
An average noise level of 55.22 db was measured for the day.								
This average holse level of 55.22 do was incastred for the day.								
Dust levels within the perimeter of the school were measured. These readings can be found								
in the chart on the next page. Daily PM 2.5 Density = 3.0, PM10 Density = 6.7								
r.8		<i></i>						
Attachments/Photos:								
Time on site: 7:00am Time off site: 3:30pm								
Inspected Work Satisfactory (Except As Noted): X No: Re-inspection Required: Work Completed:								
Inspector: Erald Hysaj Signature: Certification:								
Inspector: Erald Hysaj Signature:		Certification:						

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of $construction \ sequences. \ The field \ representative \ is \ not \ responsible \ for \ identifying \ errors \ and \ omissions \ in \ the \ contract \ documents. \ \ Rev. 11/14/17$



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT #


PHOTOS TAKEN

INSPECTION REPORT

Page	of
------	----

	T					-	
Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
02/06	08:01	Basement	1	3	7	58.1	41.2
	08:07	1st floor	2	4	9	64.2	42.1
	08:16	2nd	3	2	4	64.0	43.1
	09:43	floorBasement	4	3	6	58.2	42.1
	09:49	1st floor	5	2	5	63.2	43.2
	09:55	2nd	6	1	2	63.0	39.8
	10:02	floorBasement	7	1	2	59.1	37.5
	10:08	1st floor	8	0	1	62.2	37.6
	10:15	2nd	9	1	2	62.0	35.2
	11:43	floorBasement	10	2	5	60.1	38.9
	11:49	1st floor	11	4	9	61.8	40.2
	11:55	2nd	12	5	12	61.5	41.2
	12:02	floorBasement	13	8	17	61.2	42.1
	12:08	1st floor	14	8	19	62.1	41.8
	12:15	2nd	15	7	14	62.0	43.1
	13:43	floorBasement	16	2	5	61.5	42.5
22	13:49	1st floor	17	1	1	62.1	39.2
	13:55	2nd	18	2	4	61.0	37.5
	14:02	floorBasement	19	3	6	62.1	36.2
	14:09	1st floor	20	4	9	61.5	38.2
	14:16	2nd floor	21	1	1	61.2	39.1

Standard Sound Level Meter RealTime Graph Time: 2020-02-06 14:50:14



Start Time: 6-2-2019,8:03:11

Maxnum: 83.15 6-2-2019,10:13:12 Minnum: 42.41 6-2-2019,9:11:14

Sample Rate: 1.00 Average: 55.22 **BASEMENT HALLWAY**