

375 Rabro Drive, Hauppauge, NY 11788 • Tele: 631-761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

INSPECTION REPORT

REPORT #
112
SAMPLES TAKEN

Page of

Project:	GREENACRES ELEMENTARY SCI	Date: 03.04.2020							
A 119 19 19 19 19 19 19 19 19 19 19 19 19	11 HUNTINGTON AVENUE, SCAR		Job ID / MU #:						
G1.	ARK EAST CONSTRUCTION		Weather: SUNNY						
Inspection Type: NOISE AND DUST REPORT Contractor:									
Present At S	Site:	Sub-Contractor:							
General Are	ea:	CM/Designer:							
Specific Location: N AND S BASEMENT, 1ST FLOOR, 2ND FLOOR									
Last Inspection: Building Code Section:									
Reviewed	Drawings:	950							
Approved	Submittals								
	Other:								
Deficiency:		Resolution:							
Request For Information:									
Non-Conformance Report:									
RFI # : Issued RFI # : Answered NCR # : Issued NCR # : Resolved NCR # : Open									
Observations/Notes:									
Noise caused by ongoing construction in the perimeter of the school was monitored using									
a sound level meter. Readings were taken in the basement hallway (20 feet from									
construc	tion) next to the work performed today	у.							
An avera	age noise level of 53.368 db was meas	ured for the day.							
Dust levels within the perimeter of the school were measured. These readings can be									
found in the chart on the chart on the next page. Daily PM2.5 Density = 6.7, Daily PM10									
Density= 12.8									
Cutting concrete planks, 2 lull forklifts running, cement/mortar/grout mixer, CMU saw.									
Attachments/Photos:									
Time on site: 7:00am Time off site: 3:30pm									
Inspected Work Satisfactory (Except As Noted): X No: Re-inspection Required: Work Completed:									
Inspector: Erald Hysaj Signature: Certification:									
mspector:	Erald Hysaj Signature:		Ceruncation:						

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



375 RABRO DRIVE, HAUPPAUGE NY 11788 • TEL: (631) 761-5555 • www.mtllab.net NYC DoB Special Inspection Agency #0230

REPORT #


PHOTOS TAKEN

INSPECTION REPORT

Page of

						_	
Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
03.04	08:01	BASEMENT	1	5	9	68.2	35.8
155 1000	08:07	1ST FLOOR	2	6	10	67.5	40.2
	08:14	2ND FLOOR	3	7	13	67.0	40.9
	09:43	BASEMENT	4	3	5	69.0	36.7
	09:49	GYM	5	8	15	68.7	41.2
	09:55	2ND FLOOR	6	9	16	69.1	40.8
	10:02	BASEMENT	7	9	17	69.0	37.9
	10:08	1ST FLOOR	8	8	15	68.8	42.0
	10:15	2ND FLOOR	9	7	12	69.2	41.8
	11:43	BASEMENT	10	8	15	69.8	38.7
	11:49	1ST FLOOR	11	9	17	70.1	42.0
	11:55	2ND FLOOR	12	10	19	69.8	41.9
	12:02	BASEMENT	13	5	8	69.6	37.8
	12:08	1ST FLOOR	14	4	7	69.9	41.0
	12:15	2ND FLOOR	15	5	9	70.3	40.5
	13:43	BASEMENT	16	6	11	69.6	39.7
	13:49	1ST FLOOR	17	7	14	69.5	39.4
	13:55	2ND FLOOR	18	8	14	70.2	38.2
	14:02	BASEMENT	19	8	15	69.4	37.5
	14:08	1ST FLOOR	20	7	14	69.2	38.1
	14:15	2ND FLOOR	21	6	10	69.9	37.9

Standard Sound Level Meter RealTime Graph Time: 2020-3-4 14:45:12



Start Time: 04-03-2020,8:00:41

Maxnum: 81.10 04-03-2020,9:23:59 Minnum: 32.80 04-03-2020,9:08:21

Sample Rate: 1.00 Average: 53.68