



MUNICIPAL
TESTING LABORATORY, INC.

INSPECTION REPORT

REPORT #

SAMPLES TAKEN

Page of

Project: Greenacres School	Date: 09/11/19
Address: 41 Huntington Avenue, Scarsdale NY 10583	Job ID / MU #:
Client: Park East Construction	Weather: Sunny

Inspection Type: Noise and Dust Monitoring	Contractor: Park East
Present At Site: 7:00AM	Sub-Contractor:
General Area: Northern Yard of School	CM/Designer:
Specific Location: Northern Side of school 1st, 2nd floor, Basement	
Last Inspection:	Building Code Section:
Reviewed	Drawings:
Approved	Submittals
	Other:

Deficiency:	Resolution:			
Request For Information:				
Non-Conformance Report:				
RFI # : <input type="checkbox"/> Issued	RFI # : <input type="checkbox"/> Answered	NCR # : <input type="checkbox"/> Issued	NCR # : <input type="checkbox"/> Resolved	NCR # : <input type="checkbox"/> Open
Observations/Notes:				

Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the library, next to the work performed today.

An average noise level of 48.73 was measured today

Dust Levels within the Perimeter of the school were measured. These Readings can be found in the chart on the next page.

Work today included: Excavating dirt (CAT360), Filled dump trucks, Cutting of rebar

Attachments/Photos:

Time on site: 7:00 AM

Time off site: 3:30 PM

Inspected Work Satisfactory (Except As Noted): ☒ No: ☐ Re-inspection Required: ☐ Work Completed: ☐

Inspector: Erald Hysaj Signature:  Certification: _____

NOTICE: The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presence and activities of the field representative do not relieve the contractor's obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and means/methods of construction sequences. The field representative is not responsible for identifying errors and omissions in the contract documents. Rev.11/14/17



375 RABRO DRIVE, HAUPPAUGE NY 11788
 • TEL: (631) 761-5555 • www.mtllab.net
 NYC DoB Special Inspection Agency #0230

INSPECTION REPORT

REPORT #

PHOTOS TAKEN

Page of

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
Sept 11/19	7:37	Gym	1	2	3	74.2	75.2
	7:45	Library	2	0	1	72.1	74.0
	7:54	1st floor	3	1	2	75.8	74.0
	8:19	Library	4	0	1	73.2	75.2
	08:23	1st Floor	5	2	5	76.0	75.1
	08:30	Basement	6	1	3	74.1	70.0
	09:43	Gym	7	0	0	73.9	77.4
	09:49	1st Floor	8	1	2	75.9	74.2
	09:54	2nd Floor	9	2	5	76.5	71.8
	10:03	Basement	10	2	5	77.8	62.5
	10:09	1st Floor	11	3	8	77.9	69.1
	10:16	Cafeteria	12	1	4	78.6	69.8
	11:30	Gymnasium	13	0	1	76.4	74.2
	11:36	1st Floor	14	2	5	76.0	72.9
	11:43	cafeteria	15	2	6	76.0	72.9
	12:44	1st floor	16	2	5	76.7	74.8
	12:50	2nd floor	17	2	5	76.8	73.9
	12:57	Basement	18	1	4	77.5	69.0

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.



MUNICIPAL
TESTING LABORATORY, INC.

375 RABRO DRIVE, HAUPPAUGE NY 11788
• TEL: (631) 761-5555 • www.mtllab.net
NYC DoB Special Inspection Agency #0230

INSPECTION REPORT

REPORT #

PHOTOS TAKEN


Page of

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
Sept 11/19	13:05	Computer Room	19	1	3	78.2	66.5
	13:12	Library	20	1	3	73.0	59.7
	13:18	1st floor	21	2	5	79.4	73.4
	14:43	2nd floor	22	1	2	71.0	70.8
	14:49	Library	23	1	3	73.2	68.3
	14:56	Basement	24	1	3	75.0	69.1
	15:04	Library	25	1	2	73.0	67.8
			30				

NOTICE

The field representative is on site solely to observe operation of the contractor identified, for the work identified and it's conformance to the contract documents, and report those operations to the client. The presece and activities of the field representative do not relieve the contractor's obligation to meet the contractual requirements. Th contractor retains sole responsibility for site safety and means/methods of construction seuces. The field representative is not responsible for identifying errors and omissions in the contract documents.


Standard Sound Level Meter RealTime Graph
Time: 2019-9-11 8:13:58



Start Time: 11-09-2019,7:46:44
Maxnum: 77.60 11-09-2019,7:46:48
Minnum: 39.70 11-09-2019,7:49:14
Sample Rate: 1.00
Average: 47.49

Gymnasium AM


Standard Sound Level Meter RealTime Graph
Time: 2019-9-11 11:50:9



Start Time: 11-09-2019,8:26:56
Maxnum: 81.20 11-09-2019,9:58:47
Minnum: 35.90 11-09-2019,8:36:01
Sample Rate: 1.00
Average: 47.69

Library Data AM

Standard Sound Level Meter RealTime Graph
Time: 2019-9-12 8:4:14



Start Time: 11-09-2019,11:57:21
Maxnum: 82.50 11-09-2019,13:58:21
Minnum: 42.90 11-09-2019,14:52:34
Sample Rate: 1.00
Average: 49.60

Library