




Project: GREENACRES ELEMENTARY SCHOOL	Date: 02.25.2020
Address: 41 HUNTINGON AVENUE, SCARSDALE NY	Job ID / MU #:
Client: PARK EAST CONSTRUCTION	Weather: SUNNY

Inspection Type: NOISE AND DUST MONITOR		Contractor:	
Present At Site:		Sub-Contractor:	
General Area:		CM/Designer:	
Specific Location: S AND N BASEMENT, 1ST FLOOR, 2ND FLOOR			
Last Inspection:		Building Code Section:	
Reviewed Approved	Drawings:		
	Submittals		
	Other:		

Deficiency:		Resolution:	
Request For Information:			
Non-Conformance Report:			
RFI # : ☐ Issued	RFI # : ☐ Answered	NCR # : ☐ Issued	NCR # : ☐ Resolved
NCR # : ☐ Open			
Observations/Notes:			
Noise caused by ongoing construction in the perimeter of the school was monitored using a sound level meter. Readings were taken in the basement hallway (20 feet from construction) next to the work performed today. An average noise level of db was measured for the day. Dust level within the perimeter of the school were measured. These readings can be found in the chart on the next page. Daily PM2.5 Density= , Daily PM10 Density=			
Attachments/Photos:			
Time on site: 7:00am Time off site: 3:30pm			

Inspected Work Satisfactory (Except As Noted): ☒ No: ☐ Re-inspection Required: ☐ Work Completed: ☐

Inspector: Erald Hysaj Signature:  Certification: _____



MUNICIPAL
TESTING LABORATORY, INC.

375 RABRO DRIVE, HAUPPAUGE NY 11788
• TEL: (631) 761-5555 • www.mtllab.net
NYC DoB Special Inspection Agency #0230

INSPECTION REPORT


REPORT #

PHOTOS TAKEN

Page of

Date	Time	Location	Sample	2.5 microns	10 microns	Temp	RH%
02.25	08:11	BASEMENT	1	11	18	65.7	44.6
	08:18	1ST FLOOR	2	11	19	64.9	48.6
	08:25	2ND FLOOR	3	12	22	65.1	48.6
	09:43	BASEMENT	4	8	15	66.9	46.8
	09:49	1ST FLOOR	5	10	17	64.9	45.7
	09:55	2ND FLOOR	6	8	16	65.3	45.0
	10:02	BASEMENT	7	7	12	63.8	46.8
	10:09	1ST FLOOR	8	3	5	64.5	47.3
	10:15	2ND FLOOR	9	4	7	65.2	47.8
	11:43	BASEMENT	10	8	16	64.8	48.3
	11:49	1ST FLOOR	11	7	11	66.3	49.1
	11:55	2ND FLOOR	12	10	18	65.9	48.6
	12:02	BASEMENT	13	11	20	66.0	50.3
	12:08	1ST FLOOR	14	8	15	64.9	50.8
	12:15	2ND FLOOR	15	7	12	65.3	51.8
	14:43	BASEMENT	16	10	17	65.9	52.0
	14:49	1ST FLOOR	17	8	14	66.8	51.8
	14:55	2ND FLOOR	18	7	12	67.2	52.5
	15:02	BASEMENT	19	6	11	66.9	53.4
	15:08	1ST FLOOR	20	3	5	65.8	54.0
	15:15	2ND FLOOR	21	3	4	66.2	53.9


Standard Sound Level Meter RealTime Graph
Time: 2020-2-25 14:49:19



2ND FLOOR STORAGE

Start Time: 25-02-2020,8:08:11
Maxnum: 92.50 25-02-2020,13:10:12
Minnum: 31.30 25-02-2020,10:49:02
Sample Rate: 1.00
Average: 45.00

Standard Sound Level Meter RealTime Graph
Time: 2020-2-25 14:50:18



Start Time: 25-02-2020,8:12:00
Maxnum: 83.40 25-02-2020,9:03:10
Minnum: 31.00 25-02-2020,12:11:30
Sample Rate: 1.00
Average: 45.85

BASEMENT HALLWAY