



# SCARSDALE PUBLIC SCHOOLS

## August - 2019



**PARK EAST CONSTRUCTION**

Prepared by Francesco V. Borgese

# Table of Contents

- ▶ **Section I - Work Progress through the Month of August**

  - Greenacres Elementary School (Addition and Alterations)

  - Heathcote Elementary School (Roof Replacement)

  - Scarsdale High School (Boiler Replacement)

  - District Wide (Security Vestibules)

- ▶ **Section II - Planned work for the month of September**

- ▶ **Section III - Progress Photos**

- ▶ **Section IV - Summary of Daily Reports**



## Scarsdale Union Free School District Progress Report - Section I Greenacres Elementary School

### Work Progress - Greenacres Elementary School Addition (Phase - 1)

- New addition foundation / footing excavation - 35% Complete
- New addition footing rebar and formwork - 5% Complete
- Roadwork tie-ins - 90% Complete

### Work Progress - Greenacres Elementary School Interior Renovations (Phase - 2)

- ▶ Installation of ceiling tiles - Completed
- ▶ Painting - Completed
- ▶ Installation of ceramic tile at bathrooms - Completed
- ▶ Construction of temporary walls - Completed
- ▶ Preparation of exist. subfloor & installation of new floor - Completed
- ▶ Installation of casework - Completed
- ▶ Final connection of plumbing fixtures within casework - Completed



**Scarsdale Union Free School District  
Progress Report - Section I  
Heathcote Elementary School  
Scarsdale High School**

**Work Progress - Heathcote Elementary School**

- Demolition of existing roofing system - Completed
- Installation of new roofing system - Completed
- Installation of metal fascias - 90% Complete

**Work Progress - Scarsdale High School**

- Construction of new boilers - Completed
- Piping to new boilers - 90% Complete
- Boiler breaching - 90% Complete
- Boiler power / controls - 90% Complete



**Scarsdale Union Free School District  
Progress Report - Section II  
Greenacres Elementary School**

**Planned Work for September - Greenacres Elementary School  
Addition (Phase - I)**

- ▶ Continue excavation for proposed addition footings
- ▶ Continue installation of rebar and formwork for proposed addition footings

**Planned Work for September - Greenacres Elementary School  
Interior Renovations (Phase - II)**

- ▶ Create PEC punch list and distribute to trades



**Scarsdale Union Free School District  
Progress Report - Section II  
Heathcote Elementary School  
Scarsdale High School**

## **Planned Work for September - Heathcote Elementary School**

- Complete installation of metal fascias
- Obtain roof warranty
- Create PEC punch list and distribute

## **Planned Work for September - Scarsdale High School**

- Complete boiler piping
- Complete boiler breaching
- Complete power / controls to boilers
- Perform boiler startups





**Scarsdale Union Free School District  
Progress Pictures - Section III  
Greenacres Elementary School - Addition Phase I**



**Temporary Construction Fencing  
(Huntington Avenue)**



**Temporary Construction Fencing  
(Sage Terrace)**

August 2019



# Scarsdale Union Free School District Progress Pictures - Section III Greenacres Elementary School - Addition Phase I



Construction of Temporary Partition

August 2019



Completed Temporary Partition





**Scarsdale Union Free School District  
Progress Pictures - Section III  
Greenacres Elementary School - Addition Phase I**



**Construction of Proposed Addition  
Footing Rebar and Formwork**



**Construction of Proposed Addition  
Footing Rebar and Formwork**


August 2019



Scarsdale Union Free School District  
Progress Pictures - Section III  
Greenacres Elementary School - Interior Renovations Phase II



Typical Classroom Before  
Construction



Typical Classroom Before  
Construction





Scarsdale Union Free School District  
Progress Pictures - Section III  
Greenacres Elementary School - Interior Renovations Phase II



Typical Classroom Before  
Construction



Typical Classroom Before  
Construction



**Scarsdale Union Free School District  
Progress Pictures - Section III  
Greenacres Elementary School - Interior Renovations Phase II**



**Typical Classroom During  
Construction**



**Typical Classroom During  
Construction**

August 2019



**Scarsdale Union Free School District  
Progress Pictures - Section III  
Greenacres Elementary School - Interior Renovations Phase II**



**Typical Classroom During  
Construction**



**Typical Classroom During  
Construction**





Scarsdale Union Free School District  
Progress Pictures - Section III  
Greenacres Elementary School - Interior Renovations Phase II



Typical Renovated Classroom



Typical Renovated Classroom



**Scarsdale Union Free School District  
Progress Pictures - Section III  
Greenacres Elementary School - Interior Renovations Phase II**



**Typical Renovated Classroom**



**Typical Renovated Toilet**



## Scarsdale Union Free School District Progress Pictures - Section III Heathcote Elementary School - Roof Replacement



New Roofing System



New Roofing System and Walk Off Mats

August 2019





**Scarsdale Union Free School District  
Progress Pictures - Section III  
Heathcote Elementary School - Roof Replacement**



**New Metal Fascia**



**New Metal Fascia**



**Scarsdale Union Free School District  
Progress Pictures - Section III  
Scarsdale High School - Boiler Replacement**



**Construction of New Boilers and  
Piping**

August 2019



**Construction of New Boilers and  
Piping**





**Scarsdale Union Free School District  
Progress Pictures - Section III  
Scarsdale High School - Boiler Replacement**



**Construction of New Boiler Pumps**



**Construction of New Boiler Breaching**



## Scarsdale Union Free School District Progress Pictures - Section III District Wide - Security Vestibules



Construction of Heathcote E.S.  
Vestibule Entry

August 2019




Typical Transaction Window



## Scarsdale Union Free School District Summary of Daily Reports - Section IV Greenacres Elementary School - Additions & Alterations

### Daily Log Manpower Report

#### ▼ MANPOWER GRAPH




August 2019



# Scarsdale Union Free School District Summary of Daily Reports - Section IV Heathcote Elementary School - Roof Replacement

## Daily Log Manpower Report

### ▼ MANPOWER GRAPH




August 2019



## Scarsdale Union Free School District Summary of Daily Reports - Section IV Scarsdale High School - Boiler Replacement

### Daily Log Manpower Report

#### ▼ MANPOWER GRAPH



August 2019






## Scarsdale Union Free School District Summary of Daily Reports - Section IV District Wide - Security Vestibules

### Daily Log Manpower Report

#### ▼ MANPOWER GRAPH



August 2019